

SUMO MD MV/HV Powertrain



SUMO MD MV/HV Powertrain Troubleshooting Guide

March 2021

Safety Warnings


The description and specifications contained in the service publication are current at the time of printing. Dana TM4 reserves the right to discontinue or modify its models and/or procedures and to change specifications at any time without notice.

Any reference to brand name in this publication is made as an example of the types of tools and materials recommended for use and should not be considered an endorsement. Equivalents may be used.

IMPORTANT NOTICE

This symbol is used throughout this manual to call attention to procedures where carelessness or failure to follow specific instructions may result in personal injury and/or component damage.

Departure from the instructions, choice of tools, materials and recommended parts mentioned in this publication may jeopardize the personal safety of the service technician or vehicle operator.



WARNING: Failure to follow indicated procedures creates a high risk of personal injury to the servicing technician

CAUTION: Failure to follow indicated procedures may cause component damage or malfunction.

IMPORTANT: Highly recommended procedures for proper service of this unit

Note: Additional service information not covered in the service procedures.

Tip: Helpful removal and installation procedures to aid in the service of this unit

Always use genuine Dana TM4 replacement parts.

⚠ WARNING

This symbol is used throughout this guide to warn for electrical dangers. Failure to abide to the related safety instructions may result in personal injury and/or component damage.

Departure from the instructions, choice of tools, materials and recommended parts mentioned in this publication may jeopardize the personal safety of the service technician or vehicle operator.

Every effort has been made to endure the accuracy of all information in this guide. **However, Dana TM4 Commercial Vehicle Systems Division makes no expressed or implied warranty or representation based on the enclosed information.**

Any errors or omissions may be reported to:
Marketing Services
Dana TM4 inc.
135, Joseph-Armand Bombardier, #25
Boucherville (Québec) J4B 8P1 Canada

WARNING

This product generates high voltage that can cause an electric discharge or electrocution resulting in injury or death.

When installing the product, verify that:

- The traction battery (high-voltage battery) is disconnected.
- The auxiliary battery (12V/24V battery) is disconnected.

Care must be taken when manipulating electrical equipment.

This product must be installed by qualified and authorized personnel in accordance with applicable vehicle standards and industry practices. Always use appropriate insulation and protection before manipulating the product even when the product is disconnected from a high-voltage source.

WARNING

Mishandling of this product may damage the product and/or cause injury or death.

- All limitations and specifications communicated by Dana TM4 regarding the product must be respected.
- Do not attempt to open, repair or modify the Motor Control Unit (MCU). In case of damaged casing or suspected product malfunction, contact Dana TM4 Customer Service.
- Use only recommended points to lift and secure the MCU.
- When using straps to lift the MCU, ensure they do not touch or put pressure on any part of the product exterior (surface, connectors, and/or cables).
- Do not attach the motor to the MCU using a shared support or bracket.
- Do not apply any external load to the casing of the MCU.

WARNING

The high-voltage cables MUST be shielded:

The external cables used for high voltage must be orange and shielded; the high voltage and level of current delivered by this product can be lethal.

Failure to shield the high-voltage cables will result in non-compliance with EMI regulatory requirements.

This product uses differential mode capacitors between the positive high-voltage DC bus (+) and the negative high-voltage DC bus (-) and common mode capacitors between the high-voltage DC bus and the chassis.

Even when the product is disconnected from the high-voltage source, these capacitors can hold a voltage high enough to cause an electric discharge or death.

WARNING

Regardless of the cooling system used, when in a system, the MCU can be irreparably damaged and may become unstable if the coolant liquid pressure reaches or exceeds a pressure of 30 PSI (static pressure measured at the entrance of the MCU – upstream of the MCU in the circuit).

Ensure that the pump is adjusted accordingly.

The cooling agent contains ethylene glycol that is a highly flammable product. Ethylene glycol can burn with an invisible flame that can cause serious burns and/or other injuries.

Always handle the cooling agent carefully wearing appropriate safety clothing and eye-glasses.

The cooling agent can irritate the skin, the eyes and the mucous membranes.

- Always work in a well-ventilated area when handling the cooling agent; breathing in high concentrations of ethylene glycol can cause nausea.
- In case of contact with eyes and skin, rinse with water and consult a doctor.
- In case of ingestion, seek medical help immediately.

The cooling agent is under pressure when heated; removing the cap when the coolant is hot can cause serious burns and/or other injuries.

Wait until the coolant reaches an ambient temperature before removing the cap.

All potential dangers of handling cooling agents cannot be listed here.

Consult manufacturer warnings and recommendations for safe handling of the cooling agent.

CAUTION

It is important to ensure that no voltage is present on the high-voltage battery wires between both polarities and from each polarity to chassis before manipulation.

The vehicle integrator is responsible for ensuring that proper training is given to all those who use this system in order to avoid physical, electrical and operational hazards.

Safety Warnings.....	2	TT14: Invalid Hardware Version	87
General Information.....	6	TT15: Inconsistence of Protected EEPROM memory section	89
Acronyms - Symbols	6	TT16: Invalid Hardware or Software	91
Key Features	7	TT17: Inconsistence between Control Logic and IGBT	93
Disclaimer	8	TT18: High power battery voltage < lower voltage limit	95
Safety Instructions	8	TT19: High Power Battery Voltage > Maximum.....	99
Dana TM4 Motor and MCU Components	9	TT20: IGBT Temperature Sensor reading over the limit	105
System Specifications.....	10	TT21: Temperature Sensor reading over the limit	107
Component Description	11	TT22: EMI Temperature measurement over limit	109
Simplified System Schematic	23	TT23: Motor Coil Temperature Sensor measurement over limit	111
Diagnostics	24	TT24: High Resolver Temperature	113
Diagnostics Tool	24	TT25: Internal Software Command Not Received Properly	115
Installing the CAN drivers	26	TT26: IGBT Short Circuit Activated.....	117
Connecting the CAN ports	26	TT27: Phase Current reached Maximum	119
Opening ODIN	27	TT28: Phase Current Sum reached Maximum	121
Retrieve the SysFile ID	27	TT29: Insufficient Defluxing Current at high speed	123
SysFile ID Summary	31	TT30: AC current – Torque Mismatch.....	126
Table of SysFile ID	31	TT31: Phase Cable(s) Shorted to Chassis	133
Table of Troubleshooting Tree	31	TT32: Motor Speed reached Maximum	139
Table matching SysFile IDs and Troubleshooting Trees.....	32	TT33: Critical low frequency process overrun.....	143
Troubleshooting Tips	33	TT34: VMU Command Out-of-Range or Invalid ..	145
Service Codes	34	TT35: CAN Communication Error	147
Abbreviation and Definition	34	TT36: Position and/or Temperature Sensor Error	151
Troubleshooting Trees Tables Details	34	TT37: Sequencer error	153
Troubleshooting Tree Legends.....	35	STT01: Verify Connector Integrity.....	155
TT01: SysFile Cleared	36	STT02: Verify Cooling Circuit Integrity	157
TT02: Inconsistence in EEPROM memory section	38	Appendix	160
TT03: Vaux too low	40	Appendix 1: Table of SysFile ID.....	160
TT04: Vaux too high	46	Appendix 2: Table of Troubleshooting Trees	165
TT05: Hardware Failure Detected	51	Appendix 3: Save EEPROM Sections	171
TT06: Abnormal Battery Current Condition	57	Appendix 4: Retrieve GDD Files and User Parameters.....	172
TT07: Phase Current Sensor Deactivated.....	59	Appendix 5: Cooling agent precautions	176
TT08: HVIL voltage input fault	64	Appendix 6: Update Software	177
TT09: HVIL Output Fault.....	69		
TT10: Internal HVIL connection fault	74		
TT11: HVIL over current	78		
TT12: Initialization Timed Out.....	82		
TT13: Invalid Motor Type or Phase Calibration	85		

General Information

Acronyms - Symbols

A	Ampere unit	TM4 ODIN	Dana TM4 diagnostic software
AC	Alternative Current	USB	Universal Serial Bus
ACDC	Alternative Current to Direct Current	V	Volt unit
ASTM	American Society for Testing and Materials	Vaux	Auxiliary battery voltage (12 V or 24 V)
Auxiliary Battery	Standard 12V or 24V vehicle battery	VMU	Vehicle Management Unit
AWG	American Wire Gauge		
BIM	Battery Interface Module		
BMS	Battery Management System		
Board Net	Standard 12V or 24V vehicle network		
CAN	Control Area Network communication protocol		
CANxH	CAN x High		
CANxL	CAN x Low		
COS	Cosinus		
CRC	Cyclic Redundancy Check		
°C	Degree Celsius unit		
DC	Direct Current		
DCDC	Chopper circuit DC to DC		
DSP	Digital Signal Processor		
ECU	Electronic Control Unit		
EMF	ElectroMotive Force		
ESD	ElectroStatic Discharge		
EV	Electrical Vehicle		
GΩ	Giga Ohm unit		
GDD	TM4 ODIN Gathered Diagnostic Data sub program		
h	hour unit		
HVIL	Hazardous Voltage Interlock Loop		
HS	High Side		
kW	kiloWatt unit		
kΩ	KiloOhm unit		
mA	Milliampere unit		
L	Liter unit		
L/h	Liter per hour unit		
MΩ	Mega Ohm unit		
MCU	Motor Control Unit		
Nm	Newton meter unit		
%	Percentage		
PC	Personal Computer		
PDU	Power Distribution Unit		
POC	POwer Connector		
P/N	Part Number		
PSI	Pound-force per Square Inch unit		
PWM	Pulse Width Modulation		
RPM	Rotation Per Minute unit		
SIN	Sinus		
SysFile ID	Service Code		

Key Features

Dana TM4 Motor Control Unit (MCU)

The Motor Control Unit (MCU) system is operated via CAN message communication between the MCU and the Vehicle Management Unit (VMU) or Electronic Control Unit (ECU).

The VMU or ECU is in charge of the user interface and also interfaces with the Battery Management System (BMS) and all other systems included in the vehicle architecture.

The typical operation functions are:

- Applying power to the system from the auxiliary battery.
- Asserting the enable signal to the MCU (VMU/ECU or vehicle ignition).
- Performing high-voltage battery pre-charge (VMU/ECU or BMS).
- Applying high-voltage battery voltage to the system (BMS or BIM).
- Transmitting CAN messages (VMU/ECU) with the MCU:
 - Starting and stopping the system.
 - Applying a mechanical torque.
 - Safely shutting down the system.
 - Verifying operational status.

Hazardous Voltage Interlock Loop (HVIL)

The Hazardous Voltage Interlock Loop (HVIL) internal loop is closed, resulting in a short circuit between its two input pins. The HVIL signal is used to open the high-voltage battery contactor when its internal loop is opened during product maintenance or repair (e.g. removal of the MCU cover (MCU with removable side cover) or disconnection of motor sensor cable) thereby protecting the user.

Diagnostics Capability and Troubleshooting

Troubleshooting can be performed with the TM4 ODIN tool. It gives the list of events that occurred during the operation and categorized the events such as:

- Errors, which cause the product to cease operation.
- Warnings and Information level events are also recorded and must be taken into consideration even though the product will remain operational.

Disclaimer

Dana TM4 is not responsible for prolonged use of product with one or more defective sensors as this could cause permanent damage to the product and injury to the user. As soon as any of the system's sensors fails, the vehicle must be returned to the garage for inspection and repair.

Safety Instructions

This product must be installed and manipulated by qualified personnel who are fully aware of the types of hazards involved in working with electrical circuitry and are familiar with standard practices for preventing accidents. The vehicle integrator is responsible for ensuring that proper training is given to all those who use this system in order to avoid physical, electrical and operational hazards.

Safety warning related to operating the system

Mishandling of this product may damage the product and/or cause injury or death.

- Do not attempt to open or repair this product. In case of damaged casing or suspected product malfunction, contact Dana TM4.
- Use only recommended points to lift and secure the system.

When manipulating and/or installing this product, you must NOT:

- Modify any part of the MCU.
- Apply any external load to the casing of the MCU.

Applying excessive torque or speed when the motor is cold may negatively impact the durability of the system.


When the motor is used in an environment with an ambient temperature of below 0°C, it is recommended that you avoid using excessive speed or torque and follow a normal driving cycle for the first few minutes until the motor vehicle mechanical equipment has had a chance to warm up.

Note: This is a best practice commonly applicable to any mechanical equipment. The Dana TM4 motor does not limit performance; full speed and torque are available, but not recommended, after a cold start.

Dana TM4 Motor and MCU Components (This is an example)



Dana TM4 Motor



Dana TM4 MCU

System Specifications

The motorization system is composed of the MCU and motor.

Refer to the System Specification guide for your system.

The table below is an example.

The MCU has the following connectors:

- Communication connector.
- Grounding Point.
- DC connectors.
- Phase Connectors.
- Motor Sensor Connectors.
- Coolant IN / OUT connectors.

Characteristics	Value	
Electrical Specification		
Traction Battery		
Operating Voltage	300 - 750 V _{DC}	
Maximum non-operating voltage	775 V _{DC}	
Maximum current	615 A _{DC}	
Maximum Continuous Current	350 A _{DC}	
Auxiliary Battery		
Operational range	8 - 32 V _{DC}	
Maximum non-operating voltage	36 V _{DC}	
Maximum steady state current	4.5 A _{DC} @ 12 V _{DC} ; 3 A _{DC} @ 24 V _{DC}	
Maximum inrush current	<10 A _{DC}	
Maximum quiescent current	<0.6mA _{DC} @ 8 V _{DC} ; <1.2mA _{DC} @ 32 V _{DC}	
Maximum System Efficiency	95.3%	
CAN interface version	2.0b	
Motor Control Unit Short-Circuit Protection	Yes	
Motor Control Unit Over-Current Protection	Yes	
System Specification		
Characteristics	Designed	Measured
Maximum Mechanical Output Power	250 kW	265 kW for 47 seconds
Maximum Mechanical Output Torque	2645 Nm	2761 Nm for 30 seconds
Maximum Mechanical Output Torque at 0 RPM	2645 Nm	2731 Nm for 18 seconds
Continuous Mechanical Output Power	-	154 kW
Continuous Mechanical Output Torque	-	969 Nm
Normal Operating Range	0 - 3500 RPM	
Derating Range	3500 – 3700 RPM	
Overspeed Range	3700 – 4200 RPM for less than 2 minutes	
Environmental and cooling features		
Coolant temperature*	-40 °C to 85 °C	
Ambient temperature*	-40 °C to 85 °C	
Storage Temperature	-40 °C to 85 °C	
Cooling System	40% deionized water / 60% glycol	
Motor and MCU maximum allowed working pressure	30 PSI	
Motor Coolant Flow Rate	1200L/h	
MCU Coolant Flow Rate	1200L/h	


Component Description

Communication connector

An interface harness is used between the MCU and the VMU/ECU. The communication harness that is connected to the MCU contains all required signals to interface the MCU with the VMU/ECU, including the enable signal, the CAN ports and the CAN signals.

Type 2 connector

The communication connector has 23 pins with the following specification:



VMU/ECU interface harness – Plug pinout specifications 1-776228-1 (Type 2)


PIN	Signal Name		Types	AWG	Description
1	Ignition	Input	20-16		Enable signal to the Motor Control Unit.
2	CAN2L	Communication	20-16		Low level of differential signal CAN2.
3	CAN SHIELD	Ground/Shield	20-16		Typical CAN shield.
4	PWM1_OUT	Low side output	20-16		Generic Low side Output 1A, can be used as PWM.
5	ANALOG1	Input	20-16	-	
6	DIGITAL INPUT 1	Input	20-16	-	
7	HS_OUT	High side Output	20-16		Generic high side output 200mA.
8	Vaux+	Power	20-16		Positive power wire of the MCU. Must be connected to the auxiliary battery using fuse type.
9	CAN1L	Communication	20-16		Low level of differential signal CAN1.
10	CAN2H	Communication	20-16		High level of differential signal CAN2.
11	5V SENSOR	Analog supply	20-16	-	
12	PWM2_OUT	Low side output	20-16		Generic Low side Output 1A, can be used as PWM.
13	ANALOG3	Input	20-16	-	
14	DIGITAL INPUT 3	Input	20-16	-	
15	Vaux+	Power	20-16		Positive power wire of the MCU. Must be connected to the auxiliary battery using fuse type.
16	CAN1H	Communication	20-16		High level of differential signal CAN1.
17	GND_SENSORS	Ground	20-16	-	
18	HVIL_IN	HVIL IN	20-16		Hazardous voltage interlock loop (200mA max).
19	HVIL_OUT	HVIL OUT	20-16		Hazardous voltage interlock loop (200mA max).
20	ANALOG2	Input	20-16	-	
21	DIGITAL INPUT 2	Input	20-16	-	
22	Vaux-	Reference	20-16		Must be connected to the vehicle chassis (frame/auxiliary battery -).
23	Vaux-	Reference	20-16		Must be connected to the vehicle chassis (frame/auxiliary battery -).

Type 1 connector

The communication connector has 12 pins with the following specification:

VMU/ECU interface harness – Plug pinout specifications – P770E0106 (Type1)

PIN	Signal Name	Types	AWG	Description
A	CAN1L	Communication	20-22	Low level of differential signal CAN1.
B	CAN1H	Communication	20-22	High level of differential signal CAN1.
C	CAN2L	Communication	20-22	Low level of differential signal CAN2.
D	CAN2H	Communication	20-22	High level of differential signal CAN2.
E	Vaux+	Power	20-22	Positive power wire of the MCU. Must be connected to the auxiliary battery using fuse type.
F	Vaux+	Power	20-22	Positive power wire of the MCU. Must be connected to the auxiliary battery using fuse type.
G	Ignition	Input	20-22	Enable signal to the Motor Control Unit.
H	Emergency stop	Output	20-22	Emergency stop.
J	HVIL_IN	HVIL IN	20-22	Hazardous voltage interlock loop (200mA max).
K	HVIL_OUT	HVIL OUT	20-22	Hazardous voltage interlock loop (200mA max).
L	Vaux-	Reference	20-22	Must be connected to the vehicle chassis (frame/auxiliary battery -).
M	Vaux-	Reference	20-22	Must be connected to the vehicle chassis (frame/auxiliary battery -).





Grounding Point

The grounding point connection prevents functional issue to the motorization system, and ensures the user safety in case of an insulation fault. An incorrectly grounded connection may result in functionality losses and safety risks for the user. Grounding straps must be connected to their dedicated connection points (on the MCU and the motor) to the vehicle chassis frame.

The vehicle chassis connection points for the MCU and motor grounding straps should ideally be the same point, or the same vehicle chassis frame side. Conductive grease should be used on each of the contact points to ensure reliable and durable grounding connections. The resistance between the grounding points and the chassis must be tested each time the connection is impacted. The resistance must be less than 0.1 Ohm.


MCU and motor grounding point locations (product type example)




Motor Phase Connectors

Power cables are required between the MCU and the motor to connect each phase. An example of a product with a view of the phase cable connection points is shown below.

Phase Cable Identification (Straight Terminal)



Phase Cable Identification (90 degrees)




Motor Sensor Cables


The Motor and the MCU must be connected together by motor sensor cables. Therefore, a motor sensor interface harness is required between the motor and the MCU.

Motor sensor connector pinout mapping from Dana TM4 MCU to TM4 motors

MCU Type 1	MCU Type 2	Signal name	TM4 Motor Type 1	TM4 Motor Type 2
A	1	Temperature C-	A	F3
B	9	Temperature C+	B	F2
C	16	Temperature B-	C	A3
D	2	Temperature B+	D	A2
E	10	Temperature A-	E	A4
F	17	Temperature A+	F	B4
J	3	R1_OUT	N	A1
T	11	R2_OUT	P	B1
L	18	COS+ (S1)	L	C1
M	4	COS- (S3)	M	D1
N	12	SIN+ (S2)	J	E1
P	19	SIN- (S4)	T	F1
H	5	HVIL_TO_MOTOR	H	F4
R	13	1 Wire OUT	R	C2
S	20	1 Wire GROUND	S	C3
K	6	HVIL_FROM_MOTOR	K	E4
V	N/C	Chassis	V	N/C




MCU connector type 1




MCU connector type 2

Motor connector head Identification


Dana TM4 MCU A3 (Type 2)




Dana TM4 MCU A1/A2 (Type 1)



Dana TM4 Motor (Type 2)



Dana TM4 motor (Type 1)




Connecting Auxiliary Battery to MCU

The Auxiliary Battery provides power to the MCU. The negative terminal of the battery must be connected to the frame of the vehicle (chassis).

Auxiliary Battery Fuse

To protect the system against short circuit, a fuse is connected in series with the positive terminal of the auxiliary battery.



Specifications	Units	Values (12 V)	Values (24 V)
Maximum MCU steady state current	A	4.5	3
Maximum MCU inrush current	A	< 10	< 10
Maximum MCU quiescent current	mA	< 1	< 1.5

Note: Refer to the Installation guide for further details.

Embedded software packages

The software installation package includes several embedded files:

- The embedded software package executable
- A basic TM4 ODIN file (.odn4).

The next chart shows the embedded software package files:

File	Name	Description
Embedded Software Package Executable	MCU_INV- <i>ABCDEFGH</i> Pkg.exe (See note on software PACKAGE naming)	Embedded software files used for firmware update.
Basic TM4 ODIN file (Part of the embedded software package accessible with TM4 ODIN)	UserInterface.odn4	Basic file used within TM4 ODIN to see software variables.

Note on software package naming

A----- IGBT technology ex. HP2
 B----- Operating voltage type (L, M or H) ex. HV
 C----- Number of 3 phase systems with number of phases ex. 0206
 D----- Software develop by ex. TM4
 E----- Motor type ex MO340
 F----- Motor size ex. 240
 G ----- Software family letter ex. A
 H----- Software version (Major, minor, delivery and change list) ex. 3.6.1.95366

As an example, here is a typical software package file name:


MCU_INVHP2HV_0206_TM4_MO340_240_A_V3.6.1.95366Pkg.exe

Coolant In / Out



As power is delivered to the wheels, temperatures of the various components within the motor and the MCU rise. Therefore, a cooling unit/radiator must be installed in the vehicle and connected to the MCU and the motor to dissipate the excess heat.

The motor and the MCU are linked to the cooling system by a fan/pump/coolant tank and radiator configuration. There are two possible configurations for the cooling system: the parallel configuration and serial configuration.

Parallel Configuration



Serial Configuration



MCU example with coolant inlet and outlet indications

Coolant Specification

Safety precaution

WARNING

Regardless of the cooling system used, the product can be damaged if the coolant temperature is allowed to exceed the maximum temperature specified in your system specifications document. The MCU will apply a derating mode as a protection to reduce the system's heat generation.

Also, the static pressure of the coolant system should never be allowed to exceed 30 PSI. Doing so, may overcome internal sealing breach and cause damages to the unit:

- Ensure that the cooling system components are adjusted correctly to respect these limits.

Recommendations

To prevent corrosion in cooling systems, these recommended best practices must be followed.

- The cooling circuit must be rinsed with de-ionized water each time before filling.
- The ethylene glycol must respect the standard corresponding to its application (ASTM D3306 Type III or ASTM D6210 Type III).
- The ethylene glycol must contain some type of active corrosion inhibitors.
- The ethylene glycol must be diluted with de-ionized water (not distilled water).
- The dilution ratio must be 60% ethylene glycol to 40% de-ionized water (minimally 50% ethylene glycol to 50% de-ionized water).
- Two different types of coolant should not be mixed.

As the cooling unit, cooling hose and cooling agent are not supplied by Dana TM4, the vehicle integrator has full responsibility for following specifications and operating methods given by the system specifications and the provided products interface drawings (MCU and motor).

In order to meet Dana TM4 specifications and to obtain maximum system performance, the temperature of the coolant and coolant flow must comply with the requirements as specified in the system specifications of your system. Above these thresholds, the system can degrade the output torque to protect its internal components from overheating.

When using the MCU in a vehicle cooling configuration, there can be associated drops in pressure that have to be managed. Coolant pressure drops can be affected by the temperature of each component; refer to your system's specifications for more information.

WARNING

User security:

- Ensure that each cable is clearly identified for specific usage to prevent errors during installation and operation that may damage the system or cause injury to the user.
- Ensure that, once installed, cables do not obscure any warning labels on the product.

When installing:

- Ensure cable bending radius of x5 of the cable diameter or greater. A correctly installed cable should be smooth with no creases or signs of strain that might eventually compromise cable integrity.
- Ensure that cables do not touch or cross over each other.
- Never place cables near sharp edges or on abrasive surfaces.
- Protect cables from damage due to gravel or other environmental factors.


Allow for enough room for air circulation, clearance space for movement and access to cables for maintenance etc.

When securing cables:

- Ensure that each cable is appropriately supported (connector strain relief):
- High-voltage cables – secured no more than 10 cm from the connectors.
- Low-voltage cables – secured no more than 30 cm from the connectors.
- To restrict movement and vibration in longer cables, a maximum of 3 cables should be fastened together in parallel every 40 cm or less; do not gather cables in a tight bundle.
- Ensure that the brackets/fasteners used to support/secure the cables do not compromise cable integrity.
- Never apply perpendicular loads on the connectors/cables when using cable fasteners as this could compromise ingress protection (i.e. IP6K9K).

High Voltage Battery Terminal

The figures below show an example of an MCU cable gland where the High Voltage battery (Traction Battery) is connected.



High-voltage Battery Pre-Charge Circuit

The high-voltage battery must be connected to the MCU using specific cable assemblies. The table below is an example for the cable specifications. Refer to the MCU installation guide for the cable specifications.

Important Note: It is absolutely necessary to regard the safety precautions for the High Voltage Battery before connecting the High Voltage Cables.

The chart below is an example of the specifications available. Other system can be used with different wire size.

Specifications	Units	Values	Notes**
Wire size	AWG	1/0	1
Material	-	Under-hood contaminant resistant	1, 2
Voltage	V	Depends on high-voltage battery voltage	
Continuous current rating	A	340	3
Temperature rating	°C	150	
Colour	-	Orange	4
Shielded	-	Yes – Mandatory	5

Notes**:

1. The wire size or wire wall material can be adapted to fit required use.
2. Depending on the location of the wires, a wire tubing (orange split loom) can be used to prevent abrasion or other effects that could damage the wires.
3. Based on a temperature of 85 °C.
4. The color orange is recommended for safety purposes when handling high voltage levels.
5. The external cables used for high-voltage are be orange and shielded.

High Voltage Battery Short Circuit Protection

The MCU requires a fuse on the High Voltage DC bus. Proper fuse rating is necessary to protect against reverse polarity and short-circuit. Dana TM4 recommends installing a fuse with the following characteristics:

The table below is an example.

Specifications	Units	Values	
		CO200-MV-A1	CO200-HV-A1
Minimum fuse voltage rating	V _{dc}	650	1200
Rated current	A _{dc}	380	350
Maximum current	A _{dc}	650	650
Recommended fuse type	-	Fast-blow	Fast-blow

Refer to the "Application Note - TM4 SUMO Fuse and DC Cable Selection" published on the "Knowledge base" section of the Dana TM4 extranet site for proper fuse selection.

Diagnostics

This section covers the equipment and procedures used to diagnose the system.

Diagnostics Tool

TM4 ODIN Tool

All Events are recorded in the SysFile and can be viewed using the TM4 ODIN diagnostic tool. Events categorized as Errors are dysfunctional event and cause the product to cease operation. Warnings and Information level events are also registered. Some warnings could require to be addressed even though the system remains operational.

Requirements

There are a number of required Files and Tools in order to use the TM4 ODIN tool correctly:

- PC with Windows 10 (Windows 7, 8 with limited access).
- Software extraction .zip (7zip, WinRar...).

Note: Windows XP and lower version are no longer supported.

- Any of the supported CAN interfaces below:
 - Kvaser: USB cable interfaces.
 - PEAK System: PCAN-USB, PCAN-PCle and PCAN-USB Pro interfaces.
 - Vector: Vector XL-Interface family, for example, CANcaseXL, CANboardXL, CANcardXL and CANcardLe and the VN16XX series, are all supported by TM4 ODIN.
- Drivers appropriate to the CAN interface.
- Cable required to connect the CAN interface to the Dana TM4 product. CAN interface.
- Latest version of TM4 ODIN.

The latest version of TM4 ODIN can be downloaded from the Dana TM4 extranet:

<https://extranet.tm4.com/>

Note: Contact Dana TM4 if there is any issue during the installation or configuration of TM4 ODIN.


Note: We will refer the TM4 ODIN software by "ODIN".



Multimeter


Based upon system schematics and aided by component-specific error messages, a multimeter is required to check continuity, resistance and voltage depending of the type of investigation conducted. The multimeter can be used to check:

- Continuity
- Effective Ground connection
- Broken wires
- Open circuits
- Shorted circuits
- Incorrect voltage level (high voltage battery or Vaux)



Megohmmeter

This device is used to measure the insulation of high voltage equipment or installation that may present a safety hazard in the event of a fault. The measurement is performed by generating a high DC voltage with a specific current magnitude. The result will be displayed in $K\Omega$, $M\Omega$ or $G\Omega$.



Installing the CAN drivers

Install all the CAN drivers provided with the CAN interface onto your computer.

Note: You must have ADMIN access rights on your Windows account to be able to install the CAN drivers and you may have to reinstall or configure the CAN drivers for each USB port you want to use.

Connecting the CAN ports

Connect the CAN ports of the CAN interface to the CAN port of the Dana TM4 product. Then connect the CAN interface to your computer.

You may need an adaptor depending on the CAN interface CAN box used.

The specific characteristics for the implementation of the CAN buses are described in the technical documentation for the Dana TM4 product you are using.

Note: CAN protocol supports parallel connections. It is possible to use a CAN interface connected to a PC that includes several CAN channels connected to different CAN bus at the same time or to connect only one CAN interface channel to a CAN bus.

Opening ODIN

“ODIN 4 Server 1” is preconfigured to communicate with a MCU product by default. “ODIN 4 Server 2” is preconfigured to communicate with a Dana TM4 NEURO (VMU) by default. The ODIN 4 Servers can be reconfigured to suit customer needs.

Retrieve the SysFile ID

Retrieve the GDD files

1. Power on the unit with the appropriate Auxiliary Vehicle Battery (Vaux) supply.
2. Turn the ignition ON for the MCU to be enabled.
3. Open Odin Server 1 and establish connection to the MCU.

The Process description is in:


- Appendix 4 Retrieve GDD Files and User Parameters.

⚠ IMPORTANT

4. Make sure that at the bottom left of the Odin screen, « Device Connected » is displayed in green text.


 Device Connected

5. In Odin Server 1, in the « Package Files » dropdown menu, select « Workspaces » and then, « UserInterface.odn4 ».




- Wait until ODIN loads the following page.


Note: The following visual is an example. Other organization can be found has the software can be customized.




- In the « Diagnostic » dropdown menu, select « GDD » or click the icon in the tool bar.

Note: GDD is also available and can be invoked if a CAN trace is required.



- Click on  and browse to the folder where the .zip file is created.
- Click on the “Start” button to begin the process.

Note: If GDD was selected, a new window opens to begin the CAN trace recording.




- On the new window, click on the “Start” button (CAN trace recording start).

Note: The “Stop” button on the first window stops the CAN trace and gather the remaining information. At any time, you can click the “Abort” button on the second window to stop the process.

Once the data has been gathered, the “Email Data” button on the first window becomes available. It generates an email with the .zip. Cancel can be selected to avoid sending an email with the data right away.

SysFile ID File

1. After retrieving the GDD .zip file, extract the file “SysFile.csv”.



The screenshot shows a file explorer window with the following table of contents:

Nom	Taille	Compressé	Modifié le
SystemInfo.csv	437	316	2020-02-10...
SysFile.csv	18 234	1 587	2020-02-10...
Items.csv	61 532	8 197	2020-02-10...
BlackBox.csv	112 213	19 686	2020-02-10...

- 1 **Count:** SysFile counter.
- 2 **Event Code:** SysFile ID.
- 3 **Event Description:** Brief description of the SysFile ID.
- 4 **Event Data:** This data gives precision about the cause of event.
- 5 **Time:** Amount of time before the Event Code occurs (starting from each unit power up).
- 6 **DTC ID:** Not used
- 7 **Purposed Actions:** Not used

NOTE: Adjust column width and row height in order to view all Proposed Actions.						
1	2	3	4	5	6	7
Count	Event Code	Event Descri	Event Data	Time	DTC ID	Proposed Actions
632	0X4014	Warning - Cc	1	00:00:00	U0029-0x87	ACB2 Verify
633	0X4015	Warning - Cc	2	00:00:00	U0029-0x87	ACB2 Verify
634	0X051A	Warning - Se	0	00:00:09	0X0000-0x00	ANA No action related
635	0X051D	Info - Sequel	44487	00:00:09	0X0000-0x00	ANA No action related
636	0X051F	Info - Sequel	44487	00:00:10	0X0000-0x00	ANA No action related
637	0X3305	Info - System	44487	00:00:00	0X0000-0x00	ANA No action related
638	0X4012	Info - ComC	0	00:00:00	0X0000-0x00	ANA No action related
639	0X4014	Warning - Cc	1	00:00:00	U0029-0x87	ACB2 Verify
640	0X4015	Warning - Cc	2	00:00:00	U0029-0x87	ACB2 Verify
641	0X051A	Warning - Se	0	00:00:09	0X0000-0x00	ANA No action related
642	0X051D	Info - Sequel	44487	00:00:09	0X0000-0x00	ANA No action related
643	0X051F	Info - Sequel	44487	00:00:10	0X0000-0x00	ANA No action related
644	0X3305	Info - System	44487	00:00:00	0X0000-0x00	ANA No action related
645	0X4012	Info - ComC	0	00:00:00	0X0000-0x00	ANA No action related
646	0X4014	Warning - Cc	1	00:00:00	U0029-0x87	ACB2 Verify
647	0X4015	Warning - Cc	2	00:00:00	U0029-0x87	ACB2 Verify
648	0X051A	Warning - Se	0	00:00:09	0X0000-0x00	ANA No action related
649	0X051D	Info - Sequel	44487	00:00:09	0X0000-0x00	ANA No action related
650	0X051F	Info - Sequel	44487	00:00:10	0X0000-0x00	ANA No action related
651	0X3305	Info - System	44487	00:00:00	0X0000-0x00	ANA No action related
652	0X4012	Info - ComC	0	00:00:00	0X0000-0x00	ANA No action related
653	0X4014	Warning - Cc	1	00:00:00	U0029-0x87	ACB2 Verify

SysFile ID Summary

Note: In this document Service Code are named SysFile ID in accordance with ODIN TM4 convention.

SysFile ID are described in the Service Codes section. Some service codes identify the related system.

SysFile IDs are grouped by specific Event Categories; each SysFile ID has a unique ID and a type (Info, Warning or Error) along with a description. SysFile IDs are gathered in a Troubleshooting Tree that refer to a specific diagnostic tree.

Table of SysFile ID

The following table of the SysFile ID provides the information of the diagnostic type, the code description and the related Troubleshooting Tree (see the section **Appendix 1: Table of SysFile ID** Erreur ! Source du renvoi introuvable.in the Appendix section).

Table of Troubleshooting Tree

The table of Troubleshooting Tree provides the information of the:

- SysFile ID,
- Troubleshooting Tree number,
- Sub Troubleshooting Tree are included in some Troubleshooting Trees.

(see the section **Appendix 2: Table of Troubleshooting Trees** in the Appendix part).

Table matching SysFile IDs and Troubleshooting Trees

The following table relates the SysFile ID with the Troubleshooting Tree it belongs to.

SysFile ID	N° TT	SysFile ID	N° TT	SysFile ID	N° TT
0x0000	01	0x3201	27	0x4014	35
0x000A	02	0x3202	27	0x4015	35
0x0313	03	0x3203	28	0x4209	02
0x0314	04	0x3204	27	0x4703	35
0x0315	05	0x3205	27	0x4801	05
0x0316	05	0x3206	27	0x4B00	05
0x0319	06	0x3207	28	0x4B01	05
0x031A	07	0x3208	27	0x4B02	05
0x031B	07	0x3209	27	0x4B03	05
0x031C	07	0x320A	27	0x050B	36
0x031D	08	0x320B	28	0x050C	36
0x031E	09	0x320C	29	0x0506	37
0x031F	10	0x320D	30	0x0507	37
0x0320	11	0x320E	31	0x0508	37
0x0321	05	0x320F	23	0x0509	37
0x0322	05	0x3210	32	0x050A	37
0x0323	05	0x3211	32	0x050D	37
0x0324	05	0x3212	13		
0x0325	05	0x3301	16		
0x0326	05	0x3303	33		
0x0504	12	0x3307	14		
0x1000	15	0x3400	05		
0x1003	16	0x3401	05		
0x1100	15	0x3402	05		
0x1200	15	0x3403	05		
0x120A	13	0x3404	05		
0x1300	02	0x3405	24		
0x2200	05	0x3406	05		
0x2209	14	0x3407	05		
0x3100	17	0x3408	05		
0x3101	17	0x3500	05		
0x3102	17	0x4000	25		
0x3103	17	0x4001	34		
0x3104	17	0x4002	34		
0x3105	17	0x4003	34		
0x3106	17	0x4004	34		
0x3107	17	0x4005	34		
0x3108	17	0x4006	34		
0x3109	05	0x4007	34		
0x310A	18	0x4008	34		
0x310B	19	0x4009	34		
0x310C	19	0x400A	34		
0x310D	20	0x400B	34		
0x310E	20	0x400C	34		
0x310F	21	0x400D	34		
0x3110	21	0x400E	34		
0x3111	25	0x400F	34		
0x3112	22	0x4010	34		
0x3113	26	0x4011	34		
0x3200	27	0x4013	35		

Troubleshooting Tips

This checklist outlines some general hints and guidelines that will be helpful in tracking down and correcting operating problems.

✓ **Systems not provided by Dana TM4 are not covered in this guide**

Systems that are not provided or selected by Dana TM4 are not covered by this troubleshooting guide and might require use of additional external documentation.

✓ **Calling after-sales services**

This guide is meant to cover a dealership / garage level of troubleshooting. If the troubleshooting tree does not provide a solution to troubleshoot or solve an issue, it is highly recommended to consult after-sales services to continue troubleshooting.

✓ **A cleared code alone does not indicate a corrected problem.**

A service code is set by a specific fault condition and may be cleared by switching the ignition off, and then on. It's possible to clear an error message only to have it display again when the fault condition reoccurs. To make sure an issue is fixed, be sure to run the system through the same operating modes that caused the issue and verify that the service code does not reappear.

✓ **Electrical faults are often connection problems**

The most likely cause of electrical faults will be damaged wires or connections. As a first step in troubleshooting all electrical codes, switch off vehicle ignition and make sure that the Vaux is disconnected, then disconnect applicable connectors and inspect for damage. (Switching off the ignition and Vaux is required before disconnecting the harness at the MCU but is also a recommended practice before all other electrical system disconnections.) Clean or repair all bad connections before proceeding.

Service Codes


Abbreviation and Definition

Abbreviation	Name	Description
TT	Troubleshooting Tree	Tree that allows to diagnose the possible cause of an error, warning or information message given by the unit.
STT	Sub Troubleshooting Tree	Develops a specific and routine part of the troubleshooting tree. It is used in multiple Troubleshooting Trees (TT).
SysFile ID	Service Codes = SysFile IDs	SysFile IDs are shown by software ODIN. They describe an error, warning or information message related to the unit.

Troubleshooting Trees Tables Details


System Mode	SysFile ID	Condition	Possible Causes
Functional state of the unit when the "Condition" (dysfunctional event) occurs.	List of the Service Code/SysFile ID related to the Troubleshooting Tree (TT).	Details the dysfunctional event that occurs on the unit.	List of the possible root causes that might be the source of the dysfunctional event (determined through the TT).

Troubleshooting Tree Legends



Start & End

Indicates the beginning or end.



External Process

Indicates a process not related to this unit. It may require a specific documentation related to the unit involved.



Sub-tree

Indicates a sub-tree present in this document.




Process/Actions

Indicates any process or action to do.



Assistance Process

Indicates a process we describe an assistance action (Ex: "Call Dana TM4 for help").



Question/Decision/Choice

Indicates a decision point between two or more paths in the tree.



Document

Indicates the document to refer for a dedicated action.

TT01: SysFile Cleared

System Mode	Referred by SysFile ID	Condition	Possible Causes
ReadyToPowerOff	0x0000	Indicates that the event list has been automatically cleared. Power off the Auxiliary vehicle battery without a "Ready to Power off CAN state" of the Motor Control Unit.	<ol style="list-style-type: none"> 1. Wrong shutdown sequence. Auxiliary vehicle battery (Vaux) (12V or 24V) powered OFF before the MCU "Ready To Power OFF" CAN status on a shutdown sequence. 2. Defective MCU.

MCU power off

The MCU shall indicate the status "ReadyToPowerOff" before disconnecting power from the Auxiliary vehicle battery (Vaux) via the CAN bus. If the power is switched off before this status this SysFile ID is raised. The SysFile will be cleared. The result is loss of all the SysFile IDs recorded in the MCU.

This SysFile ID means that the event log has been cleared.

Description

This SysFile ID is raised if the MCU is switch off before the "ReadyToPowerOff" state displayed.

It may be caused by a unit shut down where the MCU did not go into the "READYTOPOWEROFF" state. It might also occur when the MCU is defective.

If SysFile section was corrupted, the SysFile is cleared. In this case, a followed warning (SysFile ID 0x000A) will indicate more detail upon nature of the clearance of the SysFile. See Subtree TT02.

Note: A manual SysFile reset by an advance user can also cause the SysFile to be cleared.

Note: On MCU shutdown sequence


The SysFile gets written in the unit EEPROM memory upon a shutdown sequence. If the Vaux power (12 V or 24 V) is removed before the MCU is in « ReadyToPowerOff » state via CAN, the SysFile section could possibly get corrupted and will be cleared on the next power ON.

Note: Refer to the Dana TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the TM4 CAN protocol document for correct MCU shutdown sequence.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.



TT02: Inconsistence in EEPROM memory section

System Mode	Referred by SysFile ID	Condition	Possible Causes
Shutdown.	0x000A 0x1300 0x4209	MCU was shut down without reaching "ReadyToPowerOff" state.	<ol style="list-style-type: none"> 1. Wrong shutdown sequence. Auxiliary vehicle battery (Vaux) (12V or 24V) powered OFF before the MCU "Ready To Power OFF" CAN status on a shutdown sequence. 2. Defective MCU.

Description

This Troubleshooting Tree 02 indicates when MCU is started up and when it is shut down, and invalid data is recorded in the EEPROM. This is discovered through the verification known as Cyclic Redundancy Check (CRC), which detects whether a SysFile entry data is corrupted.

These SysFile IDs indicate a minor issue if other subsequent power-on are shown in the SysFile history.

It may also be caused by a unit shut down where the MCU did not go into the "READYTOPOWEROFF" state.

It is less likely that these SysFile IDs would result of a defective MCU.

Note:

- Vaux must be permanent through a fuse for a successful shutdown sequence.
- Corruption of EEPROM section may occur upon writing while power (Vaux) is removed.

Note: SysFile event log only shows one « Info – System power-up ».

Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.

Related Process

The TT02 call the following process:

- Appendix 3: Save EEPROM Sections.



TT03: Vaux too low

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x0313	MCU detected an auxiliary vehicle battery voltage that was too low.	<ol style="list-style-type: none"> 1. DCDC not regulating auxiliary DC voltage correctly. 2. High auxiliary load being activated causing voltage drop. 3. The auxiliary vehicle battery does not operate correctly. 4. Intermittent or bad Vaux connection at the MCU. 5. Vaux Fuse about to open or more resistive. 6. Defective MCU.

Description

The Auxiliary vehicle battery voltage (Vaux) is the low voltage battery (12 V to 24 V) for providing power to the MCU.

This Troubleshooting Tree indicates that the voltage of the Vaux was lower than 7.5 V for at least 1 millisecond, which is the low limit for normal operation of the auxiliary vehicle battery. As this is only a warning, the system will still function as it displays this message.

The most likely cause of this warning is that the DCDC system is not regulating the auxiliary voltage correctly. It may be caused by the activation of another high auxiliary load.

The auxiliary vehicle battery itself may be defective. There may be a bad connection between the auxiliary vehicle battery and the MCU. In this case, the user may require specialized equipment to diagnose this fault. This can be also that the Vaux Fuse about to open or more resistive.

The MCU itself may be defective.


Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

VMU Connector Head Identification


VMU/ECU Interface (Type 2)



VMU/ECU Interface (Type 1)




VMU/ECU interface harness Plug Pinout (Type 2)




Connector (Front) (Type 2)


VMU/ECU interface harness Plug Pinout (Type1)



Connector (Front) (Type 1)



Wire Insertion Side (Back) (Type 2)




Wire Insertion Side (Back) (Type 1)


Connector type 2 pinout


Pin	Signal names
15	V _{AUX} +
8	
22	V _{AUX} -
23	
1	IGNITION
9	CAN1L
16	CAN1H
2	CAN2L
10	CAN2H
18	HVIL_IN
19	HVIL_OUT
5	ANALOG1
13	ANALOG3
20	ANALOG2
6	DIGITAL INPUT 1
14	DIGITAL INPUT 3
21	DIGITAL INPUT 2
7	HS_OUT
17	GND_SENSORS
3	CAN SHIELD
11	5V_SENSOR
4	PWM1_OUT
12	PWM2_OUT

Connector type 1 pinout

Pin	Signal names
E	V _{AUX} +
F	
L	V _{AUX} -(Chassis)
M	
G	IGNITION
A	CAN1L
B	CAN1H
C	CAN2L
D	CAN2H
J	HVIL
K	HVIL
H	Emergency stop







TT04: Vaux too high

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x0314	MCU detected an auxiliary voltage that was too high.	<ol style="list-style-type: none"> 1. DCDC system not regulating auxiliary DC voltage correctly. 2. Intermittent contact to the auxiliary vehicle battery that can cause voltage spikes due to load dump of the DCDC system. 3. The auxiliary vehicle battery is not working properly. 4. The MCU is defective.

Description

This Troubleshooting Tree indicates that the voltage of the auxiliary vehicle battery was higher than 33V for 1ms or more.

The most likely cause of the occurrence of this SysFile ID is that the DCDC voltage is not regulating the DC voltage correctly.

There may be intermittent contacts to the pins of the auxiliary vehicle battery.

The auxiliary vehicle battery itself may be defective.

Specialized equipment may be need to determine this and fix the issue.

The MCU itself may be defective.


Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Connector Head Identification


VMU/ECU Interface (Type 2)



VMU/ECU Interface (Type 1)




VMU/ECU interface harness Plug Pinout (Type 2)




Connector (Front) (Type 2)


VMU/ECU interface harness Plug Pinout (Type1)



Connector (Front) (Type 1)



Wire Insertion Side (Back) (Type 2)




Wire Insertion Side (Back) (Type 1)


Connector type 2 pinout

Pin	Signal names
15	V _{AUX} +
8	
22	V _{AUX} -
23	
1	IGNITION
9	CAN1L
16	CAN1H
2	CAN2L
10	CAN2H
18	HVIL_IN
19	HVIL_OUT
5	ANALOG1
13	ANALOG3
20	ANALOG2
6	DIGITAL INPUT 1
14	DIGITAL INPUT 3
21	DIGITAL INPUT 2
7	HS_OUT
17	GND_SENSORS
3	CAN SHIELD
11	5V_SENSOR
4	PWM1_OUT
12	PWM2_OUT

Connector type 1 pinout

Pin	Signal names
E	V _{AUX} +
F	
L	V _{AUX} -(Chassis)
M	
G	IGNITION
A	CAN1L
B	CAN1H
C	CAN2L
D	CAN2H
J	HVIL
K	HVIL
H	Emergency stop





TT05: Hardware Failure Detected

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x0315 0x0316 0x0321 0x0322 0x0323 0x0324 0x0325 0x0326 0x2200 0x3109 0x3400 0x3401 0x3402 0x3403 0x3404 0x3406 0x3407 0x3408 0x3500 0x4801 0x4B00 0x4B01 0x4B02 0x4B03	Internal hardware fault detection.	<ol style="list-style-type: none"> 1. Some foreign material within the MCU or motor connector short some signals. 2. MCU or motor connector pin is bent or broken. 3. Motor sensor cable defective. 4. Defective motor. 5. Defective MCU.

Description

The Troubleshooting Tree 05 indicates that there is a hardware error that may cause the system to go to defective mode, whereby it will cease operation.

Components that may be the cause of the error are:

1. Motor Temperature sensors,
2. Resolver Chip,
3. Motor position sensor.

The resistance measurements of the resistance values of the related "Machine Internal Resistances" may not be aligned as per Machine internal resistance measurement table. The motor should be considered defective.

The loss of integrity of the motor sensor connector on the MCU leads to consider defective MCU.

Note: If the motor is a TM4 machine, then the expected values of the measurements should be between 10 Ohm and 5 kOhm. If the motor is not a TM4 machine, then the measurements may be different and refer to your machine specification.

Note: Refer to the TM4 motor installation guide for more details on installation and deinstallation procedure including safety warning considerations.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.

Machine internal resistance measurement table


Machine internal resistance measurements

Pin function	Expected resistance value (see note C)	Action to perform if measurement is not as expected
R1 & R2	Measured resistance value between 10Ω and 5KΩ	Change the machine (AMA1)
S1 & S3	Measured resistance value between 10Ω and 5KΩ	Change the machine (AMA1)
S2 & S4	Measured resistance value between 10Ω and 5KΩ	Change the machine (AMA1)
Temp A- & Temp A+	See note D	Change the machine (AMA1)
Temp B- & Temp B+ (see note A)	See note D	Change the machine (AMA1)
Temp C- & Temp C+ (see note A)	See note D	Change the machine (AMA1)
Mot HVIL IN+ & Mot HVIL IN- (see note B)	Short circuit (close to 0Ω)	Change the machine (AMA1)
1Wire+ & 1Wire -	No measurement (see note E)	


Notes

- A. The TM4 machine uses 3 thermal sensors and therefore the measurements should be taken on all 3 (A, B & C). Other machine types might only use 2 (A & B) or 1 (A).
Make sure you measure the thermal resistance according to the number of thermal resistance(s) used in the machine.
Refer to 3rd party integration documentation for more information on other machine types.
- B. If the HVIL functionality is not used and therefore there is no short circuit provided between the HVIL pins inside the machine circuitry, skip this measurement.
- C. All measurements should be taken at ambient temperature.
- D. For a TM4 machine the measured resistance value should be between 10Ω and 5KΩ.
For the expected resistance value of all other machine types, refer to the 3rd party integration documentation.
- E. There are no measurements to validate the functionality related to the 1 wire pins if they are used in the machine internal circuitry.
If this circuitry is used within the machine (as it is with a TM4 machine) a malfunction involving communication with the "One wire" circuitry inside the machine will record an event in the inverter SysFile (accessible using TM4 ODIN) registered as "Warning - One-Wire EEPROM Driver...". A SysFile code ID will also be sent related to that warning to the TM4 inverter product CAN bus by the message identified as either "McuOnEventInfo1" or "Mcu On Event 1".
If such an event is recorded in the inverter SysFile and sent to the TM4 inverter product CAN bus, change the machine. (AMA1).

Connector Head Identification





TM4 Motor connector (Type 1)




TM4 Motor connector (Type 2)

Signal name	TM4 Motor connector pinout Type 1	TM4 Motor connector pinout Type 2
Temperature C-	A	F3
Temperature C+	B	F2
Temperature B-	C	A3
Temperature B+	D	A2
Temperature A-	E	A4
Temperature A+	F	B4
R1_OUT	N	A1
R2_OUT	P	B1
COS+ (S1)	L	C1
COS- (S3)	M	D1
SIN+ (S2)	J	E1
SIN- (S4)	T	F1
HVIL_TO_MOTOR	H	F4
1 Wire OUT	R	C2
1 Wire GROUND	S	C3
HVIL_FROM_MOTOR	K	E4







TT06: Abnormal Battery Current Condition

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x0319	DC battery current exceeded allowed parameters	<ol style="list-style-type: none"> 1. 0x3113 error occurred at the same time that may lead to a defective MCU 2. 0x050B error occurred at the same time that may lead to an error at the VCU/ECU level. 3. Another SysFile occurred at the same time. 4. Defective MCU.

Description

The troubleshooting tree 06 describes an error where the DC battery current exceeded the allowed parameters.

This error is likely the result of the MCU being set to Standby or failure while the vehicle was at a high speed.

The check of the Specific SysFile ID occurring at the same time of another specific SysFile ID leads to determine if the MCU is defective.

The MCU itself may be defective.


Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the Application Note High-speed fault management document.

Note: Any SysFile ID raised by the system while the vehicle is beyond the "unsafe speed" will activate the phase short circuit mechanism through the MCU power switch modules. This mechanism is activated to maintain the DC bus under the high voltage maximum limit. At the time the motor phases are short circuited through the MCU power modules, the battery current will temporarily exceed the threshold limit upon failure and raise this SysFile ID error. This error can therefore be ignored following the 0x3113 warning (TT26) "Back EMF Motor reduction mechanism activated (phases are short-circuited)". Other error(s) must be investigated.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.



TT07: Phase Current Sensor Deactivated

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x031A 0x031B 0x031C	Phase current sensor deactivated.	<ol style="list-style-type: none"> 1. If the 0x0313 SysFile occurred the same time this can be the main cause. 2. Defective DCDC system. 3. Defective auxiliary batteries. 4. Defective MCU.

Description

Troubleshooting Tree 07 indicates that one phase currents sensor(s) over three related phases are deactivated, or are faulty.

The occurrence of the SysFile ID 0x0313 at the same time of these SysFile IDs means it has to refer to the Troubleshooting Tree TT03.

The low voltage due to DCDC or the auxiliary batteries may raise to this SysFile ID.

The MCU itself may be defective.

Note: These warning indicates a fault with a particular internal phase current sensor. An internal software mechanism is put in place to ignore the reading of a particular defective phase current sensor by simulating its value according to the 2 other working phase current sensors of the same 3 phase systems keeping the system in operation.

If ever a fault occurs on another internal phase current sensor, the system will go into fault reporting other error types.


Note: Refer to the TT03 (SysFile ID 0x0313) entry for the “Vaux too low” Event for Vaux Verification and corrective actions (refer to steps in that TT03 tree that comes after voltage measurement).

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Connector Head Identification


VMU/ECU Interface (Type 2)



VMU/ECU Interface (Type 1)




VMU/ECU interface harness Plug Pinout (Type 2)




Connector (Front) (Type 2)


VMU/ECU interface harness Plug Pinout (Type1)



Connector (Front) (Type 1)



Wire Insertion Side (Back) (Type 2)




Wire Insertion Side (Back) (Type 1)


Connector type 2 pinout

Pin	Signal names
15	V _{AUX} +
8	
22	V _{AUX} -
23	
1	IGNITION
9	CAN1L
16	CAN1H
2	CAN2L
10	CAN2H
18	HVIL_IN
19	HVIL_OUT
5	ANALOG1
13	ANALOG3
20	ANALOG2
6	DIGITAL INPUT 1
14	DIGITAL INPUT 3
21	DIGITAL INPUT 2
7	HS_OUT
17	GND_SENSORS
3	CAN SHIELD
11	5V_SENSOR
4	PWM1_OUT
12	PWM2_OUT

Connector type 1 pinout

Pin	Signal names
E	V _{AUX} +
F	
L	V _{AUX} -(Chassis)
M	
G	IGNITION
A	CAN1L
B	CAN1H
C	CAN2L
D	CAN2H
J	HVIL
K	HVIL
H	Emergency stop





TT08: HVIL voltage input fault

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x031D	The HVIL circuit had a current or voltage that was outside the limits.	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not correctly configured. 2. Another system opens the HVIL loop from the HVIL input of the MCU. 3. Defective VMU/MCU interface connector on the MCU. 4. Defective MCU.

HVIL

The HVIL is short for “High Voltage Interlock Loop”. HVIL is a hardware signal, and its purpose is to protect the user. When the system is fully installed and connected, the HVIL internal loop is closed which results in a short circuit between its two input pins. The HVIL signal is used to open the high-voltage battery contactor when its internal loop is opened during product maintenance or repair (e.g. removal of MCU cover or disconnection of motor sensor cable) thereby protecting the user.

Note: Refer to the TM4 Product Operation and maintenance guide for more details.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Description

The Troubleshooting Tree 08 indicates an error where the detected voltage for the HVIL loop is outside of the limits set by the Operations and Maintenance guide.


The potential causes of this SysFile ID are listed below, in order of likelihood:

1. The HVIL parameters of the MCU are not set correctly according the user preferences, and the Operation and Maintenance guide. The HVIL parameters should be updated in the MCU.
2. There is another system that is opening the HVIL loop from the HVIL input of the MCU. To fix this fault refer to the troubleshooting guide of the other system.
3. The connectors that connect the HVIL circuit to the MCU are somehow defective. In this case, the VMU/ECU connectors must be disconnected from the MCU and repaired.
4. The MCU itself is defective. It should be disconnected and replaced.


Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Connector Head Identification


VMU/ECU Interface (Type 2)



VMU/ECU interface harness Plug Pinout (Type 2)




Connector (Front) (Type 2)




Wire Insertion Side (Back) (Type 2)

Connector type 2 pinout

Pin	Signal names
15	V _{AUX} +
8	
22	V _{AUX} -
23	
1	IGNITION
9	CAN1L
16	CAN1H
2	CAN2L
10	CAN2H
18	HVIL_IN
19	HVIL_OUT
5	ANALOG1
13	ANALOG3
20	ANALOG2
6	DIGITAL INPUT 1
14	DIGITAL INPUT 3
21	DIGITAL INPUT 2
7	HS_OUT
17	GND_SENSORS
3	CAN_SHIELD
11	5V_SENSOR
4	PWM1_OUT
12	PWM2_OUT





TT09: HVIL Output Fault

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x031E	The output of the HVIL line had a fault.	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not correctly configured. 2. Another system opens the HVIL loop from the HVIL input of the MCU. 3. Defective VMU/MCU interface connector on the MCU. 4. Defective MCU.

HVIL

The HVIL is short for “High Voltage Interlock Loop”. HVIL is a hardware signal, and its purpose is to protect the user. When the system is fully installed and connected, the HVIL internal loop is closed which results in a short circuit between its two input pins. The HVIL signal is used to open the high-voltage battery contactor when its internal loop is opened during product maintenance or repair (e.g. removal of the MCU cover or disconnection of motor sensor cable) thereby protecting the user.

Description

The troubleshooting tree 09 indicates an error where the detected high voltage for the HVIL loop is outside of the limits set by the Operations and Maintenance guide.

The potential causes of this SysFile ID are listed below, in order of likelihood:

1. The HVIL parameters of the MCU are not set correctly according the user preferences, and the Operation and Maintenance guide.
2. There is another system that is opening the HVIL loop from the HVIL output of the MCU. To fix this fault refer to the troubleshooting guide of the other system.
3. The connectors that connect the HVIL circuit to the MCU are somehow defective. In this case, the system must be turned OFF and the connectors must be repaired.
4. The MCU itself is defective, and must be replaced.

Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.


Note: Refer to the TM4 Product Operation and maintenance guide for more details.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Connector Head Identification


VMU/ECU Interface (Type 2)



VMU/ECU interface harness Plug Pinout (Type 2)




Connector (Front) (Type 2)




Wire Insertion Side (Back) (Type 2)

Connector type 2 pinout

Pin	Signal names
15	V _{AUX} +
8	
22	V _{AUX} -
23	
1	IGNITION
9	CAN1L
16	CAN1H
2	CAN2L
10	CAN2H
18	HVIL_IN
19	HVIL_OUT
5	ANALOG1
13	ANALOG3
20	ANALOG2
6	DIGITAL INPUT 1
14	DIGITAL INPUT 3
21	DIGITAL INPUT 2
7	HS_OUT
17	GND_SENSORS
3	CAN SHIELD
11	5V_SENSOR
4	PWM1_OUT
12	PWM2_OUT





TT10: Internal HVIL connection fault

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x031F	The HVIL line experienced an internal connection fault.	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not properly configured. 2. MCU phase cables not inserted properly with locking screws installed. 3. Motor phase cables not inserted properly with locking screws installed. 4. DC input cables not inserted properly with locking screws installed. 5. Motor sensor cable not properly inserted properly. 6. Defective motor sensor cable. 7. Defective motor. 8. Defective MCU.

HVIL

The HVIL is short for “High Voltage Interlock Loop”. HVIL is a hardware signal, and its purpose is to protect the user. When the system is fully installed and connected, the HVIL internal loop is closed which results in a short circuit between its two input pins. The HVIL signal is used to open the high-voltage battery contactor when its internal loop is opened during product maintenance or repair (e.g. removal of MCU cover or disconnection of motor sensor cable) thereby protecting the user.

Description

The Troubleshooting Tree 10 indicates that the HVIL lines have an internal fault. The possible causes of this error are listed below, in order of likelihood:

1. The HVIL parameters were not configured correctly. The user must access the parameters through TM4 ODIN and set them.
2. The MCU phase cables, sensor cables, or DC input cables are not inserted properly. The system must be turned OFF before the cables can be inserted and locked in again.
3. The motor sensor cable may not be fully inserted with connector locking mechanism engaged in both sides (MCU and motor). The system must be turned OFF and then the cables must be locked by the locking mechanism engaged on both sides (MCU and motor).
4. The motor is defective.
5. The MCU is defective.


Note: Refer to the TM4 Product Operation and maintenance guide for more details.


Note: Refer to the TM4 MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations


Note: Refer to the TM4 motor installation guide for more details on installation and deinstallation procedure including safety warning considerations

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.







TT11: HVIL over current

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x0320	HVIL over current fault was detected.	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not properly configured. 2. HVIL power source fault. 3. Defective MCU.

HVIL

The HVIL is short for “High Voltage Interlock Loop”. HVIL is a hardware signal, and its purpose is to protect the user. When the system is fully installed and connected, the HVIL internal loop is closed which results in a short circuit between its two input pins. The HVIL signal is used to open the high-voltage battery contactor when its internal loop is opened during product maintenance or repair (e.g. removal of MCU cover or disconnection of motor sensor cable) thereby protecting the user.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Description

The troubleshooting tree 11 indicates an error where the HVIL current was greater than the maximum allowed current. The possible causes of this error are listed below, in order of likelihood:


1. The HVIL parameters were not configured correctly. To correct this, the user must access the TM4 ODIN tool and go to the HVIL parameters to set them according to the needs and the limits set by the Operations and Maintenance Guide.
2. There is a problem with the HVIL power source that is connected to the HVIL line. This problem is external to the Motor Control Unit (MCU), refer to HVIL source Troubleshooting Guide.
3. The MCU is defective. The system must be turned OFF, and the MCU removed and replaced.

Note: Refer to the TM4 Product Operation and maintenance guide for more details.


Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Connector Head Identification


VMU/ECU Interface (Type 2)




VMU/ECU Interface (Type 1)



VMU/ECU interface harness Plug Pinout (Type 2)





VMU/ECU interface harness Plug Pinout (Type1)




Connector (Front) (Type 2)


Connector (Front) (Type 1)



Wire Insertion Side (Back) (Type 2)

Wire Insertion Side (Back) (Type 1)





TT12: Initialization Timed Out

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x0504	Initialization of Motor Control timed out, and couldn't be completed.	<ol style="list-style-type: none"> 1. Wrong motor type connected to the MCU. 2. Wrong software flashed to the MCU. 3. Defective MCU (Potential wrong factory settings).

Description

The Troubleshooting Tree 12 indicates an error where the Initialization of the MCU timed out, and couldn't be completed.

Listed below are the possible causes of this SysFile ID, in order of likelihood:

1. The wrong type of MCU is connected to your system. Check the MCU part number written on the MCU. If this is not compatible with your system installed, make sure to use the correct system with the MCU part number.
2. Check the motor part number written on the motor. If this is not compatible with your system installed, make sure to use the correct system with the motor part number.
3. The wrong software version was flashed to the MCU. In this case, check the correct software version from Dana TM4 extranet. The correct software version must be flashed to the MCU. The user must access the Dana TM4 Extranet to determine which software versions are compatible with the particular MCU
4. The MCU is defective, because the factory setting may be wrong. In this case, the MCU must be replaced.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Related Process

The TT12 call the following process:

- Appendix 6: Update Software





TT13: Invalid Motor Type or Phase Calibration

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x120A 0x3212	Invalid motor type or phase calibration.	<ol style="list-style-type: none"> 1. Third party motor not calibrated. 2. Defective motor.

Description

The Troubleshooting Tree 13 indicates an error where the Initialization of the Motor Control Unit (MCU) timed out, and couldn't be completed.

Listed below are the possible causes of these SysFile IDs, in order of likelihood:


1. The integration is using a third-party motor, which is not correctly calibrated. The user must check the Operations and Maintenance Guide to see how to calibrate the third-party motor.
2. The motor is defective. In this case, the system must be turned off, and the motor must be disconnected and replaced.

Note: Refer to the TM4 motor installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the TM4 Product installation guide (MCU and motor) for more details on installation regarding the motor sensor connection between the MCU and the motor

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT14: Invalid Hardware Version

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x3307 0x2209	The control detect that the motor connected to the MCU is not compatible with the MCU software package.	<ol style="list-style-type: none"> 1. Wrong motor type connected to the MCU. 2. Wrong software flashed to the MCU. 3. Defective Motor

Description

The Troubleshooting Tree 14 indicates an error where the motor connected to the Motor Control Unit is not compatible with the software version that the Motor Control Unit (MCU) is running.

Listed below are the possible causes of these SysFile IDs, in order of likelihood:

1. The type of motor connected to the MCU is not compatible. In this case, the user must turn off the system and disconnect and replace the motor.
2. The software version flashed to the MCU was incorrect. In this case, the user must go to the Dana TM4 extranet to find a compatible software version, and then flash it to the MCU. Refer to the Appendix 6: Update Software for the procedure to do this.
3. The motor itself may be defective.

Note: Refer to the TM4 motor installation guide for more details on installation and deinstallation procedure including safety warning considerations.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting procedure tree below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Related Process

The TT14 call the following process:

- Appendix 6: Update Software



TT15: Inconsistence of Protected EEPROM memory section

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x1000 0x1100 0x1200	Inconsistency of the Protected, Global or ParamDrv EEPROM memory section has been detected through a CRC verification.	1. Defective MCU.

Description


The Troubleshooting Tree 15 indicates an error where an inconsistency in the protected, global or ParamDrv EEPROM memory section was detected through Cyclic Redundancy Check (CRC) validation.

The possible cause of this SysFile ID may be the defective MCU. In this case, the MCU must be turned OFF and be disconnected and replaced.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT16: Invalid Hardware or Software

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x1003 0x3301	The application software flashed to the MCU is not compatible with the MCU hardware configured in factory.	<ol style="list-style-type: none"> 1. Wrong software flashed to the MCU unit (not compatible with MCU P/N). 2. Wrong MCU P/N unit used with flashed software. 3. Defective MCU (Potential wrong factory setting).

Description

The Troubleshooting Tree 16 indicates an error where the application software that was flashed to the Motor Control Unit is not compatible with the hardware configuration of the Motor Control Unit (MCU).

Listed below are the possible causes of these SysFile IDs, in order of likelihood:

1. The wrong software was flashed to the MCU, which was not compatible with the hardware's specific configuration. In this case, the user must access the Dana TM4 extranet to determine the compatibility of the software and the hardware, and determine which software version must be used.
2. The wrong MCU part number was used with the flashed software. In this case, the user must use a different MCU.
3. The MCU is defective because the factory settings are wrong. In this case, the MCU must be turned OFF and be disconnected and replaced.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Replace the MCU with a MCU corresponding to the MCU subfolder specified on the Dana TM4 extranet site.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Related Process

The TT16 call the following process:

- Appendix 6: Update Software



TT17: Inconsistence between Control Logic and IGBT

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x3100 0x3101 0x3102 0x3103 0x3104 0x3105 0x3106 0x3107 0x3108	Inconsistency between the internal control logic and the turn ON of IGBT of phase #1 to phase # 9 respectively.	<ol style="list-style-type: none"> 1. Minor issue. Could potentially be raised due to internal noise under high DC input voltage level. 2. Defective MCU, if 0x320D SysFile ID also occurs within the same power up. 3. Defective MCU, if 0x3200 to 0x3208 SysFile ID also occurs within the same power up.

Description

The Troubleshooting Tree 17 indicates an error where there is an inconsistency between the internal control logic of the MCU and the activation of the IGBT of one or more phases.

Listed below are the possible causes of these SysFile IDs, in order of likelihood:


1. It may be a minor issue, and may be seen because of internal noise, and no action may be needed.
2. The MCU may be defective. In this case, the MCU must be turned OFF and the MCU must be disconnected and replaced.

This event indicates inconsistency between the internal control logic and the turn ON of IGBT of the related phase.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT18: High power battery voltage < lower voltage limit

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x310A	The high-power DC voltage dropped under the limit and caused the system to go in a fault state.	<ol style="list-style-type: none"> 1. DC high power contactor issue. 2. DC high power battery source issue. 3. DC high power battery chain connection issue (contactor, PDU, pre-charge circuit and MCU, BMS). 4. Improper grounding (MCU and / or motor). 5. DC system load activation/deactivation. 6. Defective controller. 7. Defective MCU.

Description

The Troubleshooting Tree 18 indicates an error where the High-Power DC voltage drops lower than the limit (300V), which caused the system to go in a defective state.

Listed below are the possible causes of the SysFile ID, in order of likelihood:

1. Something is wrong with the main contactors of the lines from the DC high power battery.
2. There is an issue with the DC high power battery source. The user must consult the manual related to the DC high voltage battery.
3. DC high power battery chain connection issue (contactor, PDU, pre-charge circuit and MCU, BMS). Check the continuity along the cables from MCU to High Voltage Battery pack. If there is continuity fault, replace the wirings.
4. There is an issue with the grounding. In this case, the system must be turned OFF and the grounding connections must be checked. If they are defective, replace the grounding wirings.
5. There are additional loads on board the vehicle that might trigger the SysFile ID. Refer to the potential external causes list in the Note.
6. Connect TM4 ODIN to check if these SysFile IDs occur again. If this is the case, the MCU is defective. Turn Ignition OFF and all high voltage electrical sources before replacing MCU.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations

Note: List of potential external causes:


- Another defective system on the DC bus causing electrical overloads,
- Defective Battery Management System or Battery Interface Module,
- Defective battery contactor causing intermittent contact,
- Defective controller VMU/ECU,
- Higher than normal High Voltage battery level,
- Defective Power Distribution Unit or connection between MCU and Power Distribution Unit,
- Defective battery charger.


Refer to the related Service Manual of these listed systems.


Note: Refer to the Battery Pack Troubleshooting Guide to get the pinout of the related Battery Pack connector to perform the correct continuity check.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.







TT19: High Power Battery Voltage > Maximum

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x310B 0x310C	High power DC voltage was higher than the limit.	<ol style="list-style-type: none"> 1. "BlackBox info available" is not displayed in the status bar at the bottom of the window in TM4 ODIN tool 2. Significant voltage drops meaning numerous repeated connections and reconnections. 3. Affected motor resolver signal (motor angle waveform) that creates DC high voltage ripple. 4. Continuity fault between the MCU grounding port and the ground. 5. Another external root causes. 6. Defective MCU.

Description

The troubleshooting tree 19 indicates an error where the high power DC battery voltage reaches over voltage limit and causes MCU defective state.

Listed below are the possible artifacts of these SysFile IDs in order of likelihood:

1. The text "BlackBox info available" is not displayed in the status bar at the bottom of the window in TM4 ODIN tool.
2. There were significant voltage drops within the BlackBox view meaning there were numerous repeated connections and reconnections.
3. The motor resolver angle waveform shows ripples. See the note and the pictures on the next page.
4. There is continuity fault between the MCU grounding port and the ground.
5. There is continuity fault between the shield portion DC cables connected to the DC cable glands assemblies (positive and negative cables).
6. Another external root causes.
7. Connect TM4 ODIN to check these SysFile IDs occur again. If this is the case, the MCU is defective.

Note: The DC high battery power lines have a contactors issue. Turn Ignition off before investigation of the contactors. For the investigation refer to the relevant contactor documentation.

Note: The DC high voltage supply is intermittent. Turn Ignition off before the investigation of the DC battery chain from the contactor to the MCU.

Note: There are resonance within the DC lines or the regeneration torque causes increase in voltage because of battery resistance or the motor resolver is making a voltage ripple.

Note: Regarding contact intermittence to MCU, if the contactor contacts or any other contacts in the battery chain from contactor to MCU are intermittent while the MCU is in operational state, it could make the DC bus to fluctuate due to resonances on the DC line beyond the high voltage detection point.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the TM4 Product installation guides for more details on grounding (MCU and motor).




To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.


Note: Regarding the resolver angle waveform, if the MCU goes in faulty state, it will capture a BlackBox upon the reported error(s).


The BlackBox can then be consulted via ODIN tool to see if the angle waveform (saw tooth) is straight on each rising and falling edges.


See below examples of waveform.











TT20: IGBT Temperature Sensor reading over the limit

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x310D 0x310E	One of the temperature sensors of the IGBT went over the limit and caused the system to go in a fault state.	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit. 5. Phase cable are damaged. 6. Wrong torque applied to one or many phase lugs. 7. Wrong phase cable crimping. 8. Defective MCU.

Description

The Troubleshooting Tree 20 indicates an error where one of the temperature sensors had a reading where the temperature was higher than the allowed maximum temperature and causes MCU defective state.

Listed below are the possible artifacts of these SysFile IDs in order of likelihood:

1. The loss of the cooling circuit integrity. Refer to the Sub Troubleshooting Tree STT02 Verify Coolant integrity of the motor and MCU cooling circuit.
2. There are signs of burnt spots on the MCU contacts and on the phase cables. Or, the wrong torque was used on one or more of the phase lugs, and / or, the wrong phase cable crimping on one or more of the phase lugs.
3. Connect TM4 ODIN to check if these SysFile IDs occur again. If this is the case, the MCU is defective. Turn Ignition OFF and all high voltage electrical sources before replacing MCU.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: There is air in the cooling circuit. The air must be let out of the cooling circuit.

Note: The flow of the cooling liquid is too low to cool the motor. Refer to the cooling system troubleshooting Guide.


Note: The temperature of the liquid temperature is too high to cool the motor. The system must turn Ignition off and the coolant mixture must be replaced.

Note: The mixture of the cooling liquid was done badly, which does not let the coolant cool the motor. Replace the mixture of cooling liquid. Refer to the cooling system Service Manual.

Note: The wrong phase cable crimping on one or more of the phase lugs. Replace the cable.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT21: Temperature Sensor reading over the limit

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x310F 0x3110	One of the internal temperature sensors went over the limit and caused the system to go in a failure state.	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high. 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Defective MCU.

Description

The Troubleshooting Tree 21 indicates an error where one of the temperature sensors had a reading where the temperature was higher than the maximum limit and causes MCU defective state.

Listed below are the possible artifacts of this error, in order of likelihood:

1. The loss of the cooling circuit integrity. Refer to the Sub Troubleshooting Tree STT02 Verify Coolant integrity of the motor and MCU cooling circuit.
2. Connect TM4 ODIN to check if these SysFile IDs occur again. If this is the case, the MCU is defective. Turn Ignition OFF and all high voltage electrical sources before replacing MCU.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations

Note: There is air in the cooling circuit. The air must be let out of the cooling circuit.


Note: The flow of the cooling liquid is too low to cool the motor. Refer to the cooling system troubleshooting Guide.

Note: The temperature of the liquid temperature is too high to cool the motor. The system must be turned off and the coolant mixture must be replaced.

Note: The mixture of the cooling liquid was done badly, which does not let the coolant cool the motor. Replace the mixture of cooling liquid. Refer to the cooling system Service Manual.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT22: EMI Temperature measurement over limit

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x3112	The internal EMI section temperature measurement went over the limit and caused the system to go in a fault state.	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high. 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Wrong torque applied to one or both DC lugs. 6. Wrong DC cable crimping. 7. Defective MCU.

Description

The Troubleshooting Tree 22 indicates an error where an internal temperature sensor had a reading which was greater than the limit, and causes MCU defective state.

Listed below are the possible artifacts of this SysFile ID, in order of likelihood:

1. The loss of the cooling circuit integrity. Refer to the Sub Troubleshooting Tree STT02 Verify Coolant integrity of the motor and MCU cooling circuit.
2. There are signs of burnt spots on the MCU contacts and on the phase cables. Or, the wrong torque was used on one or more of the phase lugs, and / or, the wrong phase cable crimping on one or more of the phase lugs.
3. Connect TM4 ODIN to check if these SysFile IDs occur again. If this is the case, the MCU is defective. Turn Ignition OFF and all high voltage electrical sources before replacing MCU.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: There is air in the cooling circuit. The air must be let out of the cooling circuit.

Note: The flow of the cooling liquid is too low to cool the motor. Refer to the cooling system troubleshooting Guide.


Note: The temperature of the liquid temperature is too high to cool the motor. The system must turn Ignition off and the coolant mixture must be replaced. Refer to the cooling system Service Manual.

Note: The mixture of the cooling liquid was done badly, which does not let the coolant cool the motor. Replace the mixture of cooling liquid. Refer to the cooling system Service Manual.

Note: The wrong phase cable crimping on one or more of the phase lugs. Replace the cable.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT23: Motor Coil Temperature Sensor measurement over limit

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x320F	One of the temperature sensors of the motor coil went over the limit and caused the system to go in a failure state.	<ol style="list-style-type: none"> 1. Another SysFile occurred (TT05) 2. Air in the cooling circuit. 3. Cooling liquid flow too low or nil (cooling pump issue). 4. Cooling liquid temperature too high 5. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 6. Active short circuit mechanism activated (for more than 2 minutes without speed reduction under safe back EMF voltage). 7. Defective motor.

Description

The Troubleshooting Tree 23 indicates an error where one of the temperature sensors of the motor coil had a reading where the temperature was greater than the maximum limit and causes MCU defective state.

Listed below are the possible artifacts of this SysFile ID, in order of likelihood:

1. The SysFile IDs occur in the same time as 0x320F, refer to the TT05.
2. The loss of the cooling circuit integrity. Refer to the Sub Troubleshooting Tree STT02 Verify Coolant integrity of the motor and MCU cooling circuit.
3. The motor is hot. The short circuit protection was turned on for more than 2 minutes. Wait the motor cooling down.
4. When the motor is cooled down, turn Ignition on. Connect TM4 ODIN to check if this SysFile ID occurs again. If this is the case, the MCU is defective. Turn Ignition OFF and all high voltage electrical sources before replacing MCU.

Note: Refer to the motor installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the Application Note High-speed fault management document.

Note: There is air in the cooling circuit. The air must be let out of the cooling circuit.


Note: The flow of the cooling liquid is too low to cool the motor. Refer to the cooling system troubleshooting Guide.

Note: The temperature of the liquid temperature is too high to cool the motor. The system must turn Ignition off and the coolant mixture must be replaced. Refer to the cooling system Service Manual.

Note: The mixture of the cooling liquid was done badly, which does not let the coolant cool the motor. Replace the mixture of cooling liquid. Refer to the cooling system Service Manual.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT24: High Resolver Temperature

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x3405	The Resolver Converter Chip detected a resolver chip high temperature.	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high. 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Defective MCU.

Description

The Troubleshooting Tree 24 indicates an error where the resolver converter chip detected high temperature for the resolver chip.

The Motor and MCU cooling circuit is a possible cause of this SysFile ID. If this is the case, refer to the Sub Troubleshooting Tree STT02 to verify the cooling circuit integrity of the motor and MCU cooling circuit.

The MCU itself may also be defective.

Note: Refer to the motor installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: There is air in the cooling circuit. The air must be let out of the cooling circuit.


Note: The flow of the cooling liquid is too low to cool the motor. Refer to the cooling system troubleshooting Guide.

Note: The temperature of the liquid temperature is too high to cool the motor. The system must turn Ignition off and the coolant mixture must be replaced. Refer to the cooling system Service Manual.

Note: The mixture of the cooling liquid was done badly, which does not let the coolant cool the motor. Replace the mixture of cooling liquid. Refer to the cooling system Service Manual.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics



TT25: Internal Software Command Not Received Properly

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x3111 0x4000	An internal software command mechanism was not received properly.	<ol style="list-style-type: none"> 1. Software problem. Update inverter software. 2. Defective MCU

Description

The Troubleshooting Tree 25 indicates an error where a software command was not received correctly in the MCU.

These SysFile IDs is a software version issue. The user must update the software of the MCU to the last version published in Dana TM4 extranet. The MCU itself may also be defective.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Related Process

The TT25 call the following process:

- Appendix 6: Update Software



TT26: IGBT Short Circuit Activated

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x3113	The IGBT short circuit mechanism has been activated. This event is normally a reaction to another event.	1. Other error causes the system to move in defective while in high speed (back EMF too high to maintain DC bus under the high voltage limit).

Description

The Troubleshooting Tree 26 indicates an error where the IGBT short circuit mechanism was activated, in reaction to another event.

Other error caused the MCU defective while operating at a high speed, (back Electro-mechanical Feedback is too high to maintain DC bus under the high voltage limit).

MCU must have been commanded to shut down by the VMU /ECU (via CAN bus) while the vehicle was beyond the "unsafe speed". Refer the Troubleshooting Guide of the VMU /ECU for investigation of the causes.

Note: Back EMF Motor reduction mechanism

Any error event raised by the system while the motor speed is beyond the "unsafe speed" will activate the phase short circuit mechanism through the MCU power switch modules. This mechanism is activated to maintain the DC bus under the high voltage maximum limit until the motor speed is reduced under the « unsafe speed ».


At the time the motor phases are short circuited, it is normal that the phase currents and potentially the input DC current will temporarily exceed the limits and raise these errors type.

Other error(s) must be investigated.

Note: Refer to the Application note High-Speed fault Management Document.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.



TT27: Phase Current reached Maximum

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x3200 0x3201 0x3202 0x3204 0x3205 0x3206 0x3208 0x3209 0x320A	One or more of the phase currents reached the maximum design threshold.	<ol style="list-style-type: none"> 1. Short circuit between phases. 2. The auxiliary vehicle battery not operating correctly. 3. Intermittent or bad Vaux connection at the MCU. 4. Vaux Fuse about to open or more resistive. 5. An external error was caused by VMU/ECU. 6. Defective MCU.

Description

The Troubleshooting Tree 27 indicates an error where the current in one or more of the phase cables were at the maximum design threshold.

This SysFile may be raised by Back EMF Motor reduction mechanism or warning of the Motor-Control Inverter 0x00 to 08 or by a connector issue.

The low Vaux may raise these SysFile IDs, refer to the Troubleshooting tree TT03.

An external error from VMU/ECU can be a cause. It must be investigated.

The MCU itself may be defective.

Note: If the auxiliary vehicle battery system is defective turn Ignition off and high voltage electrical sources, refer to the auxiliary vehicle battery Troubleshooting Guide.


Note: The Vaux fuse connecting the auxiliary vehicle battery became more resistive, or about to open. In this case, turn Ignition OFF and all high voltage electrical sources, refer to the auxiliary vehicle battery or Low Voltage distribution board Troubleshooting Guide.

Note: Back EMF Motor reduction mechanism
If any error type is raised by the system while the motor speed is beyond the « unsafe speed », the motor phases will be short circuited by the control to maintain DC bus under the high voltage limit until the motor speed is reduced below the « unsafe speed ». At the time the motor phases are short circuited, it is normal that the phase currents and potentially the input DC current will temporarily exceed the limits and raise these errors type.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT28: Phase Current Sum reached Maximum

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x3203 0x3207 0x320B	The phase 1-2-3, 4-5-6, or 7-8-9 current sum reached the maximum limit.	<ol style="list-style-type: none"> 1. The auxiliary vehicle battery not operating correctly. 2. Intermittent or bad Vaux connection at the MCU. 3. Vaux Fuse about to open or more resistive. 4. Defective MCU.

Description

The troubleshooting tree 28 indicates a warning where the sum of the phase currents of phases trios 1-2-3, 4-5-6, and/or 7-8-9 are equal to or higher than the maximum limit.

This SysFile may be raised by “Warning - Vaux too low” under the same « Info - System power up » as « phase current reached the maximum ».

The MCU itself may be defective.


Note: Note on Vaux level too low.

If the Vaux level is too low, the current sensors used for the phase current readings could saturate and falsely interpret the current

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



TT29: Insufficient Defluxing Current at high speed

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x320C	There is not enough defluxing current at high speed.	<ol style="list-style-type: none"> 1. MCU temperature too high for the motor speed (verify cooling). 2. Motor temperature too high for the motor speed (verify cooling). 3. Defective MCU. 4. Defective motor.

Description

The Troubleshooting Tree 29 indicates an error where the defluxing current is not large enough when the motor speed is at high speed level.

The cooling circuit issue may raise this SysFile ID.

A road test discriminates defective Motor and defective MCU from cooling circuit issue. Another road test discriminates the motor from the MCU defectives.

Note: on this error type


This error type indicates that there is not enough defluxing current at high speed. The point of over speed can dynamically be reduced due to overheat of the MCU or motor. If one of those components is overheating, there might be not enough defluxing current at high speed and this error will be raised.

Note: Refer to the TM4 ODIN technical guide for more information.

Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.



References

Name	Value	Hex Value
Rx		
Tx		
McuCommand1Response		
McuCommand2Response		
McuInfo1		
McuInfo2		
McuEventInfo1		
McuThermal1		
DriveCoolingFlowRequest	0	00000000
MotorCoolingFlowRequest	0	00000000
ThermalIndicator	0	00000000
Polling		



Parameters System Status **CAN Interface** Manual Control Calibration Identification

TT30: AC current – Torque Mismatch

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x320D	The reference torque is not matching with the estimated torque (most of the time lower than reference).	<ol style="list-style-type: none"> 1. Phase cable lugs not properly assembled on inverter or motor. 2. Wrong phase cables order. 3. Motor resolver signal incoherence (intermittence signal, distorted signal). 4. Defective MCU.

Description

The Troubleshooting Tree 30 indicates an error where the level of torque to the motor doesn't match the amount of power delivered by the AC current.

The Connections between the motor and the MCU, and the damaged phase cables or motor sensor cables defectives may cause the SysFile ID. The incorrect connection configuration (Standard or Reverse) of the phase cables may cause the issue. The loss of sensor connector integrity may cause the SysFile ID.

All the phase cables and their connection on the MCU and the motor are needed to be fully functional and complying to the installation manual.

TM4 ODIN diagnostic tool allows to visualize the motor resolver angle waveform: see next page.

The MCU itself may be defective.

Note: Refer to the TM4 Product installation guide and operation and maintenance manual for more details on the phase cables configurations and parameter setting.

Note: Refer to the motor installation guide for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the Dana TM4 product(s) MCU installation guide(s) for more details on installation and deinstallation procedure including safety warning considerations.

Note: If the MCU goes in failure, it will capture a BlackBox upon the high voltage battery reached the high limit error. The BlackBox can then be consulted via ODIN tool to see if the angle waveform (saw tooth) is straight on each rise and fall edges.



To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.


Note: Regarding the resolver angle waveform, if the MCU goes in faulty state, it will capture a BlackBox upon the reported error(s).


The BlackBox can then be consulted via ODIN tool to see if the angle waveform (saw tooth) is straight on each rising and falling edges.


See below examples of waveform.














TT31: Phase Cable(s) Shorted to Chassis

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x320E	The system detected an insulation issue in-between the AC and the chassis or between the DC and chassis.	<ol style="list-style-type: none"> 1. Another system on the same DC bus had a sudden loss of insulation 2. Outdate software. 3. Damaged phase cables. 4. Defective connector causing the short circuit. 5. Defective MCU. 6. Defective motor.

Description

The Troubleshooting Tree 31 indicates an error where the cables (AC or DC) connecting the Motor and the MCU were shorted to the chassis, possibly due to a cable insulation problem.

Other systems on the same DC bus that reports a loss of insulation that could affect the MCU.

A MCU software upgrade might be more filtering concerning the detection of short circuits.

A damaged phase cable might be causing the error to be raised.

A sudden loss of insulation for system connected to the high voltage DC bus may occur.

The DC and phase connectors integrity loss or foreign material inside the connections might be causing the short circuits.

The MCU and/or the motor themselves may be defective.

Note: on the phase to chassis detection

The input DC voltage is electrically insulated from the chassis. A fast transient towards the chassis voltage level caused by another equipment can potentially trigger the fault. Software upgrade might solve the issue providing more filtering to the detection.

Note: on the phase to chassis detection

A fast transient of more than 100 V / 10µs caused by another equipment can potentially trigger the fault. Software upgrade might solve the issue providing more filtering to the detection.

Note: Refer to the Dana TM4 Product installation guides for more details on installation and deinstallation procedure including safety warning considerations.

Note: Refer to the TM4 Product Interface drawing for more details on torque requirement

Note: on the phase cables

Ensure that the manufacturer of the cable is one of the recommended cables:

- SD-10402-16 Marking EVRP-150 1AWG from OMG,
- EXTRAD XLE 155/XLE 1 AWG Shielded Cable from Champlain,
- 150 HVFX-XLE from Champlain.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.


Related Process


The TT31 call the following process:


- Appendix 6: Update Software











TT32: Motor Speed reached Maximum

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x3210 0x3211	The motor speed reached its limit in forward or backward direction and caused the system to go in a failure state	<ol style="list-style-type: none"> 1. Motor speed is too high - Torque derated but something else preventing the speed to reduce. 2. MCU speed setting parameters wrongly configured (start, end and speed limit derating in forward or backward direction). 3. Defective MCU. 4. Defective motor resolver.

Description

The Troubleshooting Tree 32 indicates an error where the motor speed reached the maximum speed, in either direction, which cause the system to go into the defective state.

The maximum speed for the motor depends on your system application. With ODIN tool check the value of the forward and backward max speed and compare them to your specific system specifications or the preset values from the Operation and Maintenance guide.

The maximum speed limit might be reached while the truck was in a downhill. It is possible the driver uses the mechanical brakes to slow down the vehicle.

The motor sensor cable or the motor sensor connector on the MCU or the motor might cause the issue.

The MCU and/or the motor resolver themselves may be defective.

Note: If the MCU goes in failure, it will capture a BlackBox upon the high voltage battery reached the high limit error. The BlackBox can then be consulted via ODIN tool to see if the angle waveform (saw tooth) is straight on each rise and fall edges.

Note: Note on the maximum speed parameters
By default, the maximum speed parameters (Motor.SpDfwdMax and Motor.SpdBwdMax) are set to the maximum speed the system can achieve. They can be set to lower values by the customer. The maximum speed fault will therefore trigger when the speed (forward or backward) reach the parameter setting (forward or backward).

Note: Refer to the Operation and Maintenance guide for more details on the speed parameters settings.

Note: Refer to the System Specification document for more details on Overspeed range limit.

Note: on maximum speed reached
It is possible to reach maximum speed limit regardless of the speed derating in the case the vehicle is going down a downhill slope and the mechanical brake are not used to slow down the vehicle. In this case, it is imperative that the driver act on the mechanical brakes to slow down the vehicle. The back EMF at speeds higher than the overspeed range of the system could potentially damage the MCU.



To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.


Note: Regarding the resolver angle waveform, if the MCU goes in faulty state, it will capture a BlackBox upon the reported error(s).

The BlackBox can then be consulted via ODIN tool to see if the angle waveform (saw tooth) is straight on each rising and falling edges.

See below examples of waveform.







TT33: Critical low frequency process overrun

System Mode	Referred by SysFile ID	Condition	Possible Causes
Defective	0x3303	The internal software process exceeded its processing limit.	<ol style="list-style-type: none"> 1. No issue. Warning listed as error if reported at time 0:00:00 after power up. 2. MCU software error.

Description

The Troubleshooting Tree 33 indicates an error where the internal software process reached its processing limit and can't perform any more tasks.

If the SysFile ID was raised at 00:00 seconds after start up this event is a minor event, this should be considered as a warning.

If the SysFile occurred after 00:00 seconds then the MCU software might be outdated. After updating the MCU software if there are more occurrences contact Dana TM4 to continue troubleshooting.

Note: regarding the SysFile

If that error is listed as the first event at 0:00 second from the unit power ON, this event can be considered as a warning and does not affect functionality. Otherwise, if this error is listed at time > 0:00 second, this event will put the MCU in error.

Note: regarding this type of error

If the software is the latest version as published on the Dana TM4 extranet site and this error is listed at > 0:00 second after the « Info – System power-up » event, this indicates that there is an issue with the software.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the procedure of troubleshooting tree below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Related Process

The TT33 call the following process:

- Appendix 6: Update Software



TT34: VMU Command Out-of-Range or Invalid

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x4001 0x4002 0x4003 0x4004 0x4005 0x4006 0x4007 0x4008 0x4009 0x400A 0x400B 0x400C 0x400D 0x400E 0x400F 0x4010 0x4011	VMU command is out of range or is invalid.	1. Verify MCU CAN protocol document for protocol requirements.

Description

The Troubleshooting Tree 34 indicates an error where the command from the VMU is either out of range or is an invalid command.

The command did not match what was required by the CAN protocol.

The CAN network might cause the issue fixed. Refer to the CAN protocol document published on the Dana TM4 extranet site.

Note: Refer to the CAN protocol document as published on the Dana TM4 extranet site.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Troubleshooting Tree 34

Set the CAN protocol of the device communicating with the MCU.

Refer to the CAN protocol document as published on the Dana TM4 extranet site.

TT35: CAN Communication Error

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x4013 0x4014 0x4015 0x4703	VMU command timed out. Sequencer Detected a CAN Communication Error	<ol style="list-style-type: none"> 1. Verify MCU CAN protocol document for protocol requirements (controller issue). 2. Defective CAN connection (Cable or harness). 3. Defective CAN network. 4. Defective MCU.

Description

The Troubleshooting Tree 35 indicates a warning where the VMU command is timed out because it was not received within the CAN timeout limit. The sequencer detected a CAN communication error.

There may be an issue with the controller. Make sure the controller complies to the CAN protocol defined in the CAN protocol document when communication with the MCU.

The VMU/ECU harness interface connector for integrity loss might be causing an error in the CAN communications.

The CAN network might cause the issue fixed. Refer to the CAN protocol document published on the Dana TM4 extranet site.

The MCU itself may be defective.

Note: Refer to the CAN protocol document as published on the Dana TM4 extranet site.

Note: on CAN termination on a CAN bus



For optimised communication on a CAN bus, there should be a termination resistor of 120 ohms between the CAN lines (high and low) at one end of the CAN bus and another termination resistor of 120 ohms between the CAN lines at the other end of the CAN bus. This makes a resultant end termination of 60 ohms.

Note: Refer to the MCU installation guide for more details on installation and deinstallation procedure including safety warning considerations

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics

Connector type 1 and type 2 pinouts.

Connector type 1		Connector type 2	
			
Pin	Signal names	Pin	Signal names
E	V _{AUX} +	15	V _{AUX} +
F		8	
L	V _{AUX} -(Chassis)	22	V _{AUX} -
M		23	
G	IGNITION	1	IGNITION
A	CAN1L	9	CAN1L
B	CAN1H	16	CAN1H
C	CAN2L	2	CAN2L
D	CAN2H	10	CAN2H
J	HVIL	18	HVIL_IN
K	HVIL	19	HVIL_OUT
H	Emergency stop	5	ANALOG1
		13	ANALOG3
		20	ANALOG2
		6	DIGITAL INPUT 1
		14	DIGITAL INPUT 3
		21	DIGITAL INPUT 2
		7	HS_OUT
		17	GND_SENSORS
		3	CAN SHIELD
		11	5V_SENSOR
		4	PWM1_OUT
		12	PWM2_OUT


Expected resistance measurement between CAN ports.


CAN port measurements

Measure between (See note 1)	Measurement detail	Expected resistance value
CAN1 low to CAN1 high	CAN termination of CAN port 1 (Differential measurement)	120 Ω \pm 5% (See note 2)
CAN2 low to CAN2 high	CAN termination of CAN port 2 (Differential measurement)	2.6 K Ω \pm 5%
CAN1 low to MCU chassis	Common mode measurement of CAN1 low	> 60 K Ω
CAN1 high to MCU chassis	Common mode measurement of CAN1 high	> 60 K Ω
CAN2 low to MCU chassis	Common mode measurement of CAN2 low	> 60 K Ω
CAN2 high to MCU chassis	Common mode measurement of CAN2 high	> 60 K Ω

Note

1. The pinout information can also be found in the MCU installation guide.
2. Depending of the product type, the CAN termination resistance of CAN port 1 can be 2.6 K Ω \pm 5%.





TT36: Position and/or Temperature Sensor Error

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x050B 0x050C	Deactivation process couldn't be successfully executed or timeout occurred while going in the deactivation process.	<ol style="list-style-type: none"> 1. The VMU/ECU has sent a shutdown request to the MCU during operation, causing this error to be raised. 2. Defective MCU.

Description

The event category 36 indicates a warning where the Position sensor and/or the temperature sensors are having errors.

The SysFile IDs occur in the same session (under the same "Info – System Power Up") as the "Back EMF Motor reduction mechanism activated (phases are short-circuited)" error.

The VMU/ECU might have sent a shutdown request to the MCU while the motor speed was greater than given threshold.

The MCU itself may be defective.

Note: on shutdown request while vehicle speed is high


The ECU / VMU controller must have sent a shutdown sequence request via CAN message to the MCU that caused the warning

« Back EMF Motor reduction mechanism^[1] activated (phases are short-circuited) »" to be raised while the motor speed was greater than the threshold of that warning. The ECU / VMU controller could have registered a fault at its level and shutdown the MCU. In that case, the source of the problem must be investigated at the ECU / VMU controller level.

Note: Refer to the Application Note High-speed fault management document.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics



TT37: Sequencer error

System Mode	Referred by SysFile ID	Condition	Possible Causes
Operational	0x0506 0x0507 0x0508 0x0509 0x050A 0x050D	This error is activated by a lower level error.	1. Some other error caused the SysFile to be raised.

Description

The event category 37 shows a sequencer type error.

These errors are caused by a lower level error type and refer to the errors raised under the same "Info-System power-up".

Note: on Sequencer error type

Most of «Sequencer » types errors are considered top level errors. They are triggered from a lower level error type

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the troubleshooting tree procedure below.

See "Safety Warnings" and "Troubleshooting Tips" sections for general guidelines on system diagnostics.

Troubleshooting Tree 37



Refer to the Troubleshooting Trees associated with the SysFile ID that were also raised under the same « Info - System power-up » to continue troubleshooting.

STT01: Verify Connector Integrity

Related TT	External input	Outcome
TT03 TT04 TT05 TT08 TT09 TT10 TT27 TT28	None.	1. The connectors have been replaced.

Description

The sub troubleshooting tree “Verify Connector Integrity” deals with the issue where the connectors of different parts of the MCU must be repaired or replaced.

Note: Refer to the TM4 Product installation guide for more details on product connector pinout information.

One pin in bent or broken as well the conductivity fault cause defective MCU and involve in several Troubleshooting Trees.

TM4 ODIN diagnostic tool helps to determine the harness connector faulty.

There is Amphenol connector (see picture on this page) and not Amphenol connector.
The connector is an Amphenol connector, a pin might tend to move toward inside the related system.
For connector not Amphenol connector, pull gently the pin until the locking mechanism engaged.

Note: Refer to the TM4 Product installation guide for more details on installation and deinstallation procedure including safety warning considerations.


Note: Refer to the TM4 Product installation guide for more details on product connector pinout information.

To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the procedure of troubleshooting tree below.

See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Amphenol type connector:





STT02: Verify Cooling Circuit Integrity

Related TT	External input	Outcome
TT20 TT21 TT22 TT23 TT24 TT29	None.	<ol style="list-style-type: none"> 1. The cooling system has no problems and can be left alone. 2. The cooling hoses have a problem and must be physically oved or replaced. 3. The coolant mixture is not the correct mixture, and it must be replaced. 4. There is an issue with the radiator.

Description

The sub troubleshooting tree “Verify Cooling Circuit Integrity” deals with the issue where the cooling circuit of the motor and the Motor Control Unit (MCU) must be checked and, if necessary, repaired or replaced.

The lack of coolant, the air within the motor an MCU lead to the system overheat.

A slowdown cooling flaw in the cooling circuit leads to the system overheat.

The cooling agent mixture shall comply with the TM4 Product installation manual recommendations and integration vehicle installation manual.

Note: Refer to integration vehicle installation manual.

Note: Refer to the TM4 Product installation guide for more details on cooling agent mixture.

Note: On cooling agent
Wrong cooling agent can create dust / rust in the cooling circuit.


To correctly diagnose the faulty system, connect the Diagnostic Tool (see «Diagnostics» section for test equipment and descriptions) and follow the procedure of troubleshooting tree below.


See “Safety Warnings” and “Troubleshooting Tips” sections for general guidelines on system diagnostics.

Related Process

The STT02 call the following process:

- Appendix 5: Cooling agent precautions.





Appendix

Appendix 1: Table of SysFile ID

The following table of the SysFile ID gives the information of the diagnostic type, the code description and the related Troubleshooting Tree.

SysFile ID	Diagnostic Type	Description	Troubleshooting Tree
0x0000	Info	SysFile 0x0000 - SysFile cleared	01
0x000A	Warning	SysFile 0x0A	02
0x0313	Warning	Board 0x13 - VAUX too low	03
0x0314	Warning	Board 0x14 - VAUX too high	04
0x0315	Warning	Board 0x15 motor temp sensor shorted to -Vaux	05
0x0316	Warning	Board 0x16 motor temp sensor open or shorted to +Vaux	05
0x0319	Error	Board 0x19 - Abnormal battery current condition as not operational	06
0x031A	Warning	Board #26 - Phase current sensor deactivated (phase 1, 2 or 3)	07
0x031B	Warning	Board #27 - Phase current sensor deactivated (phase 4, 5 or 6)	07
0x031C	Warning	Board #28 - Phase current sensor deactivated (phase 7, 8 or 9)	07
0x031D	Error	Board 0x1D - HVIL voltage input fault	08
0x031E	Error	Board 0x1E - HVIL voltage output fault	09
0x031F	Error	Board 0x2F - HVIL internal fault	10
0x0320	Error	Board 0x20 - HVIL over current	11
0x0321	Warning	Board 0x21 motor temperature sensor A1 was shorted to -Vaux.	05
0x0322	Warning	Board 0x22 motor temperature sensor A1 was disconnected or shorted to +Vaux.	05
0x0323	Warning	Board 0x23 motor temperature sensor B1 was shorted shorted to -Vaux.	05
0x0324	Warning	Board 0x24 motor temperature sensor B1 was disconnected or shorted to +Vaux.	05
0x0325	Warning	Board 0x25 motor temperature sensor C1 was shorted shorted to -Vaux.	05
0x0326	Warning	Board 0x26 motor temperature sensor C1 was disconnected or shorted to +Vaux.	05
0x0504	Error	Sequencer 0x04 - Initialisation timed out	12
0x1000	Error	NvdGlobalSection #1	15
0x1003	Error	NvdGlobalSection #4	16
0x1100	Error	NvdProtectedSection 0x00	15
0x1200	Error	ParamDrv 0x00	15
0x120A	Error	ParamDrv 0x0A - Invalid phase calibration	13
0x1300	Warning	NvdSavSection 0x00	02

SysFile ID	Diagnostic Type	Description	Troubleshooting Tree
0x2200	Warning	ParamMac 0x00	05
0x2209	Error	ParamMac 0x09 - Unsupported motor hardware version	14
0x3100	Warning	Motor Control Inverter 0x00	17
0x3101	Warning	Motor Control Inverter 0x01	17
0x3102	Warning	Motor Control Inverter 0x02	17
0x3103	Warning	Motor Control Inverter 0x03	17
0x3104	Warning	Motor Control Inverter 0x04	17
0x3105	Warning	Motor Control Inverter 0x05	17
0x3106	Warning	Motor Control Inverter 0x06	17
0x3107	Warning	Motor Control Inverter 0x07	17
0x3108	Warning	Motor Control Inverter 0x08	17
0x3109	Error	Motor Control Inverter 0x09 - Position sensor hardware fault	05
0x310A	Error	Motor Control Inverter 0x0A - High power battery voltage reached the low limit	18
0x310B	Error	Motor Control Inverter 0x0B - High power battery voltage reached the high limit	19
0x310C	Error	Motor Control Inverter 0x0C - High power battery voltage reached the high limit (H/W detection)	19
0x310D	Error	Motor Control Inverter 0x0D - Temperature too high	20
0x310E	Error	Motor Control Inverter 0x0E - Temperature too high	20
0x310F	Error	Motor Control Inverter 0x0F - Temperature too high	21
0x3110	Error	Motor Control Inverter 0x10 - Temperature too high	21
0x3111	Error	Motor Control Inverter 0x11 - Invalid command	25
0x3112	Error	Motor Control Inverter 0x12 - Temperature too high	22
0x3113	Warning	Motor Control Inverter 0x13 - Back EMF Motor reduction mechanism activated (phases are short-circuited)	26
0x3200	Error	Motor Control Machine 0x00 - MCU phase #1 current reached the maximum	27
0x3201	Error	Motor Control Machine 0x01 - MCU phase #2 current reached the maximum	27
0x3202	Error	Motor Control Machine 0x02 - MCU phase #3 current reached the maximum	27
0x3203	Warning	Motor Control Machine 0x03 - Sum of MCU phase #1_2_3 currents exceeds maximum limit	28
0x3204	Error	Motor Control Machine 0x04 - MCU phase #4 current reached the maximum	27
0x3205	Error	Motor Control Machine 0x05 - MCU phase #5 current reached the maximum	27

SysFile ID	Diagnostic Type	Description	Troubleshooting Tree
0x3206	Error	Motor Control Machine 0x06 - MCU phase #6 current reached the maximum	27
0x3207	Warning	Motor Control Machine 0x07 - Sum of MCU phase #4_5_6 currents exceeds maximum limit	28
0x3208	Error	Motor Control Machine 0x08 - MCU phase #7 current reached the maximum	27
0x3209	Error	Motor Control Machine 0x09 - MCU phase #8 current reached the maximum	27
0x320A	Error	Motor Control Machine 0x0A - MCU phase #9 current reached the maximum	27
0x320B	Warning	Motor Control Machine 0x0B - Sum of MCU phase #7_8_9 currents exceeds maximum limit	28
0x320C	Error	Motor Control Machine 0x0C	29
0x320D	Error	- Motor Control Machine 0x0D	30
0x320E	Error	Motor Control Machine 0x0E - Insulation to chassis fault	31
0x320F	Error	Motor Control Machine 0x0F - Motor temperature	23
0x3210	Error	Motor Control Machine 0x10 - Speed reached its limit in forward direction	32
0x3211	Error	Motor Control Machine 0x11 - Speed reached its limit in backward direction	32
0x3212	Error	Motor Control Machine 0x12 - Invalid motor phase	13
0x3301	Error	Application in Safe Mode	16
0x3303	Error	Application 0x03	33
0x3307	Warning	Invalid Motor Hardware Version	14
0x3400	Warning	Resolver #1 - Parity error	05
0x3401	Warning	Resolver #2 - Abnormal signals	05
0x3402	Warning	Resolver #3 - Broken cos line	05
0x3403	Warning	Resolver #4 - Broken sin line	05
0x3404	Warning	Resolver #5 - Abnormal conversion	05
0x3405	Warning	Resolver #6 - Resolver high temperature	24
0x3406	Warning	Resolver #7 - Delta angle too high	05
0x3407	Warning	Resolver #8 - Resolver errHld pin raised	05
0x3408	Error	Resolver #9 - Position sensor module error	05
0x3500	Warning	One-Wire EEPROM Driver 0x00 - Device presence not detected	05
0x4000	Error	ComClient 0x00 - No CAN mailbox are available for the adapter to use	25
0x4001	Warning	ComClient 0x01 - VmuCommandSafety TorqueCommand is out of range	34
0x4002	Warning	ComClient 0x02 - VmuCommandSafety SpeedCommand is out of range	34

SysFile ID	Diagnostic Type	Description	Troubleshooting Tree
0x4003	Warning	ComClient 0x03 - VmuCommandSafety CommandMode is invalid	34
0x4004	Warning	ComClient 0x04 - VmuCommand2 TorqueCommand is out of range	34
0x4005	Warning	ComClient 0x05 - VmuCommand2 SpeedCommand is out of range	34
0x4006	Warning	ComClient 0x06 - VmuCommand2 CommandMode is invalid	34
0x4007	Warning	ComClient 0x07 - VmuCommand2 OperationalMode is invalid	34
0x4008	Warning	ComClient 0x08 - VmuCommand1 OperationRequest is invalid	34
0x4009	Warning	ComClient 0x09 - VmuCommand1 MinBatteryVoltage voltage is out of range	34
0x400A	Warning	ComClient 0x0A - VmuCommand1 MaxBatteryVoltage voltage is out of range	34
0x400B	Warning	ComClient 0x0B - VmuCommand1 MaxDischargeCurrent is out of range	34
0x400C	Warning	ComClient 0x0C - VmuCommand1 MaxChargeCurrent is out of range	34
0x400D	Warning	ComClient 0x0D - Safety check, delta too high between CommandMode	34
0x400E	Warning	ComClient 0x0E - Safety check, delta too high between SpeedCommand	34
0x400F	Warning	ComClient 0x0F - Safety check, delta too high between TorqueCommand	34
0x4010	Warning	ComClient 0x10 - The library cannot decode the received data	34
0x4011	Warning	ComClient 0x11 - A message received had the wrong DLC	34
0x4013	Warning	ComClient 0x13 - VmuCommand1 timeout	35
0x4014	Warning	ComClient 0x14 - VmuCommand2 timeout	35
0x4015	Warning	ComClient 0x15 - VmuCommandSafety timeout	35
0x4209	Warning	NvdBlackboxSection #10	02
0x4703	Error	GDMGR 0x03 - CAN communication error	35
0x4801	Error	(Position sensor error: verify previous warnings)	05
0x4B00	Warning	CoilTempSensorMgr 0x00 - Motor temperature sensor A1 is invalid	05
0x4B01	Warning	CoilTempSensorMgr 0x01 - Motor temperature sensor B1 is invalid	05
0x4B02	Warning	CoilTempSensorMgr 0x02 - Motor temperature sensor C1 is invalid	05
0x4B03	Warning	CoilTempSensorMgr 0x03 - None of the motor temperature sensors is valid	05

SysFile ID	Diagnostic Type	Description	Troubleshooting Tree
0x050B	Error	Sequencer 0x0B – Deactivation failed. This vent indicates that the deactivation process couldn't be successfully executed.	36
0x050C	Error	Sequencer 0x0C – Deactivation timed out. This event indicates that a timeout occurred while going in the deactivation process.	36
0x0506	Error	Sequencer 0x06 – Motor control in wrong state.	37
0x0507	Error	Sequencer 0x07 – Activation failed.	37
0x0508	Error	Sequencer 0x08 – Activation timed out.	37
0x0509	Error	Sequencer 0x09 – Motor control in wrong state.	37
0x050A	Error	Sequencer 0x0A – Motor control in wrong state.	37
0x050D	Error	Sequencer 0x0D – System error.	37

Appendix 2: Table of Troubleshooting Trees

The following table of the SysFile ID gives the information of the diagnostic type, the code description and the related Troubleshooting Tree.

Troubleshooting Tree	SysFile IDs	Causes (numbered in order of likely occurrence)
01	0x0000	<ol style="list-style-type: none"> 1. Wrong shutdown sequence. Auxiliary vehicle battery (Vaux) (12V or 24V) powered OFF before the MCU "Ready To Power OFF" CAN status on a shutdown sequence. 2. Defective MCU.
02	0x000A 0x1300 0x4209	<ol style="list-style-type: none"> 1. Wrong shutdown sequence. Auxiliary vehicle battery (Vaux) (12V or 24V) powered OFF before the MCU "Ready To Power OFF" CAN status on a shutdown sequence. 2. Defective MCU.
03	0x0313	<ol style="list-style-type: none"> 1. DCDC not regulating auxiliary DC voltage correctly. 2. High auxiliary load being activated causing voltage drop. 3. The auxiliary vehicle battery does not operate correctly. 4. Intermittent or bad Vaux connection at the MCU. 5. Vaux Fuse about to open or more resistive. 6. Defective MCU.
04	0x0314	<ol style="list-style-type: none"> 1. DCDC system not regulating auxiliary DC voltage correctly. 2. Intermittent contact to the auxiliary vehicle battery that can cause voltage spikes due to load dump of the DCDC system. 3. The auxiliary vehicle battery is not working properly. 4. The MCU is defective.

Troubleshooting Tree	SysFile IDs	Causes (numbered in order of likely occurrence)
05	0x0315 0x0316 0x0321 0x0322 0x0323 0x0324 0x0325 0x0326 0x2200 0x3109 0x3400 0x3401 0x3402 0x3403 0x3404 0x3406 0x3407 0x3408 0x3500 0x4801 0x4B00 0x4B01 0x4B02 0x4B03	<ol style="list-style-type: none"> 1. Some foreign material within the MCU or motor connector short some signals. 2. MCU or motor connector pin is bent or broken. 3. Motor sensor cable defective. 4. Defective motor. 5. Defective MCU.
06	0x0319	<ol style="list-style-type: none"> 1. 0x3113 error occurred at the same time that may lead to a defective MCU 2. 0x050B error occurred at the same time that may lead to an error at the VCU/ECU level. 3. Another SysFile occurred at the same time. 4. Defective MCU
07	0x031A 0x031B 0x031C	<ol style="list-style-type: none"> 1. If the 0x0313 SysFile occurred the same time this can be the main cause. 2. Defective DCDC system. 3. Defective auxiliary batteries. 4. Defective MCU.
08	0x031D	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not correctly configured. 2. Another system opens the HVIL loop from the HVIL input of the MCU. 3. Defective VMU/MCU interface connector on the MCU. 4. Defective MCU.
09	0x031E	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not correctly configured. 2. Another system opens the HVIL loop from the HVIL input of the MCU. 3. Defective VMU/MCU interface connector on the MCU. 4. Defective MCU

Troubleshooting Tree	SysFile IDs	Causes (numbered in order of likely occurrence)
10	0x031F	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not properly configured. 2. MCU phase cables not inserted properly with locking screws installed. 3. Motor phase cables not inserted properly with locking screws installed. 4. DC input cables not inserted properly with locking screws installed. 5. Motor sensor cable not properly inserted properly. 6. Defective motor sensor cable. 7. Defective motor. 8. Defective MCU.
11	0x0320	<ol style="list-style-type: none"> 1. MCU HVIL parameters were not properly configured. 2. HVIL power source fault. 3. Defective MCU.
12	0x0504	<ol style="list-style-type: none"> 1. Wrong motor type connected to the MCU. 2. Wrong software flashed to the MCU. 3. Defective MCU (Potential wrong factory settings).
13	0x120A 0x3212	<ol style="list-style-type: none"> 1. Third party motor not calibrated. 2. Defective motor.
14	0x3307 0x2209	<ol style="list-style-type: none"> 1. Wrong motor type connected to the MCU. 2. Wrong software flashed to the MCU. 3. Defective Motor
15	0x1000 0x1100 0x1200	<ol style="list-style-type: none"> 1. Defective MCU.
16	0x1003 0x3301	<ol style="list-style-type: none"> 1. Wrong software flashed to the MCU unit (not compatible with MCU P/N). 2. Wrong MCU P/N unit used with flashed software. 3. Defective MCU (Potential wrong factory setting).
17	0x3100 0x3101 0x3102 0x3103 0x3104 0x3105 0x3106	<ol style="list-style-type: none"> 1. Minor issue. Could potentially be raised due to internal noise under high DC input voltage level. 2. Defective MCU, if 0x320D SysFile ID also occurs within the same power up. 3. Defective MCU, if 0x3200 to 0x3208 SysFile ID also occurs within the same power up.

Troubleshooting Tree	SysFile IDs	Causes (numbered in order of likely occurrence)
	0x3107 0x3108	
18	0x310A	<ol style="list-style-type: none"> 1. DC high power contactor issue. 2. DC high power battery source issue. 3. DC high power battery chain connection issue (contactor, PDU, pre-charge circuit and MCU, BMS). 4. Improper grounding (MCU and / or motor). 5. DC system load activation/deactivation. 6. Defective controller. 7. Defective MCU.
19	0x310B 0x310C	<ol style="list-style-type: none"> 1. "BlackBox info available" is not displayed in the status bar at the bottom of the window in TM4 ODIN tool 2. Significant voltage drops meaning numerous repeated connections and reconnections. 3. Affected motor resolver signal (motor angle waveform) that creates DC high voltage ripple. 4. Continuity fault between the MCU grounding port and the ground. 5. Another external root causes. 6. Defective MCU.
20	0x310D 0x310E	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Phase cable are damaged. 6. Wrong torque applied to one or many phase lugs. 7. Wrong phase cable crimping. 8. Defective MCU.
21	0x310F 0x3110	<ol style="list-style-type: none"> 1. . Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high. 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Defective MCU.
22	0x3112	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high. 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Wrong torque applied to one or both DC lugs. 6. Wrong DC cable crimping. 7. Defective MCU.
23	0x320F	<ol style="list-style-type: none"> 1. Another SysFile occurred (TT05) 2. Air in the cooling circuit. 3. Cooling liquid flow too low or nil (cooling pump issue). 4. Cooling liquid temperature too high 5. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 6. Active short circuit mechanism activated (for more than 2 minutes without speed reduction under safe back EMF voltage). 7. Defective motor.

Troubleshooting Tree	SysFile IDs	Causes (numbered in order of likely occurrence)
24	0x3405	<ol style="list-style-type: none"> 1. Air in the cooling circuit. 2. Cooling liquid flow too low or nil (cooling pump issue). 3. Cooling liquid temperature too high. 4. Wrong cooling agent mixture used – (can create dust/rust in the cooling circuit). 5. Defective MCU .
25	0x3111 0x4000	<ol style="list-style-type: none"> 1. Software problem. Update inverter software. 2. Defective MCU
26	0x3113	<ol style="list-style-type: none"> 1. Other error causes the system to move in defective while in high speed (back EMF too high to maintain DC bus under the high voltage limit).
27	0x3200 0x3201 0x3202 0x3204 0x3205 0x3206 0x3208 0x3209 0x320A	<ol style="list-style-type: none"> 1. Short circuit between phases. 2. The auxiliary vehicle battery not operating correctly. 3. Intermittent or bad Vaux connection at the MCU. 4. Vaux Fuse about to open or more resistive. 5. An external error was caused by VMU/ECU. 6. Defective MCU.
28	0x3203 0x3207 0x320B	<ol style="list-style-type: none"> 1. The auxiliary vehicle battery not operating correctly. 2. Intermittent or bad Vaux connection at the MCU. 3. Vaux Fuse about to open or more resistive. 4. Defective MCU.
29	0x320C	<ol style="list-style-type: none"> 1. MCU temperature too high for the motor speed (verify cooling). 2. Motor temperature too high for the motor speed (verify cooling). 3. Defective MCU. 4. Defective motor.
30	0x320D	<ol style="list-style-type: none"> 1. Phase cable lugs not properly assembled on inverter or motor. 2. Wrong phase cables order. 3. Motor resolver signal incoherence (intermittence signal, distorted signal). 4. Defective MCU
31	0x320E	<ol style="list-style-type: none"> 1. Another system on the same DC bus had a sudden loss of insulation 2. Outdate software. 3. Damaged phase cables. 4. Defective connector causing the short circuit. 5. Defective MCU. 6. Defective motor.


Troubleshooting Tree	SysFile IDs	Causes (numbered in order of likely occurrence)
32	0x3210 0x3211	<ol style="list-style-type: none"> 1. Motor speed is too high - Torque derated but something else preventing the speed to reduce. 2. MCU speed setting parameters wrongly configured (start, end and speed limit derating in forward or backward direction). 3. Defective MCU. 4. Defective motor resolver.
33	0x3303	<ol style="list-style-type: none"> 1. No issue. Warning listed as error if reported at time 0:00:00 after power up. 2. MCU software error.
34	0x4001 0x4002 0x4003 0x4004 0x4005 0x4006 0x4007 0x4008 0x4009 0x400A 0x400B 0x400C 0x400D 0x400E 0x400F 0x4010 0x4011	<ol style="list-style-type: none"> 1. Verify MCU CAN protocol document for protocol requirements.
35	0x4013 0x4014 0x4015 0x4703	<ol style="list-style-type: none"> 1. Verify MCU CAN protocol document for protocol requirements (controller issue). 2. Defective CAN connection (Cable or harness). 3. Defective CAN network. 4. Defective MCU.
36	0x050B 0x050C	<ol style="list-style-type: none"> 1. The VMU/ECU has sent a shutdown request to the MCU during operation, causing this error to be raised. 2. Defective MCU.
37	0x0506 0x0507 0x0508 0x0509 0x050A 0x050D	<ol style="list-style-type: none"> 1. Some other error caused the SysFile to be raised.

Appendix 3: Save EEPROM Sections

1. Power-on the unit with appropriate Vaux supply
2. Open Odin Server 1 and establish connection to the MCU.
3. Make sure that at the bottom left of the Odin screen, « Device Connected » is displayed in green text.
4. In Odin Server 1, in the « Package Files » dropdown menu, select « Workspaces » and then, « UserInterface.odn4 ».
5. When the workspace has finished loading, in the watch window, select the « Parameters » tab. Then click the (+) at the left of all the subfolders.
6. Change any of the desired parameter(s) by double clicking on its value field and by changing its value. Once the value is changed, select the keyboard enter key or click elsewhere on the ODIN window so the value is written.

Note: The parameters in the Motor subfolder cannot be changed. They are "read only" by the user.

7. Once all the desired parameters have been changed, change the value field of the « DrvParameters.Save » to 1 and wait until it comes back to 0 by itself.
8. Follow recommended power-off and power-on cycle to ensure that the unit has properly saved All EEPROM sections. The new parameters will take effect in the MCU control only on the next power ON.
9. It is possible to save all the parameters under Drive subfolder in one file that could be used to upload in another MCU. First, delete the Motor subfolder since this cannot be exported and written to another motor. At this point, right-click in the watch window and select « Export Values to File ... ». You are then asked to select the filename and its location. This will save the file with an .odni extension.
10. The .odni file can therefore be imported in another enabled MCU via the Import Values... located within the ODIN File menu. Once imported, select OK at the pop up window.
11. At this point, change the value field of the « DrvParameters.Save » to 1 and wait until it comes back to 0 by itself.
12. Follow recommended power-off and power-on cycle to ensure that the unit has properly saved All EEPROM sections. The new parameters will take effect in the MCU control only on the next power ON



Appendix 4: Retrieve GDD Files and User Parameters

1. Power-on the unit with appropriate Auxiliary Vehicle Battery (Vaux) supply.
2. Open Odin Server 1 and establish connection to the MCU.
3. Make sure that at the bottom left of the Odin screen, « Device Connected » is displayed in green text.
4. In Odin Server 1, in the « Diagnostic » dropdown menu, select « GDD » and then, click the « ... ».


Note: This will allow you to select the location of where the Motor Control Unit GDD (Gathered Diagnostic Data) File will be saved.

Note: If you didn't succeed to retrieve the GDD Files and user parameters, notify to Dana TM4 and continue further down the troubleshooting tree


5. Open Odin Server 1 and establish connection to the ACDC controller of the unit.
6. Make sure that at the bottom left of the Odin screen the message, « Device Connected », shows up green.




7. In Odin Server 1, in the « Package Files » dropdown menu, select « Workspaces » and then, « UserInterface.odn4 ».




8. Wait until TM4 ODIN load the following page.




9. Make sure you are connected to the product using TM4 ODIN by checking that the bottom left of the Odin screen, « Device Connected » is displayed in green text.
10. In the « Diagnostic » dropdown menu, select « GDD ».



11. Wait until TM4 ODIN load the following page.



12. On the Parameters Tab, right click the select "Export Values To File..."



Appendix 5: Cooling agent precautions

Safety precaution

WARNING

It is mandatory to proceed with caution when connecting and disconnecting the system. All precautions should be observed to prevent any infiltration of coolant into the electrical connections. The electrical property of the coolant will cause electrical malfunction and may cause permanent damages to the unit. Make sure that the electrical connectors and the coolant connectors are never open at the same time.

Connectors should be capped with adequate protection as soon as possible after they are disconnected. Connectors should be connected as soon as possible after their protective caps are removed.

Cooling inlet/outlet hoses Safety precautions

WARNING

Following standard practice safety precautions are mandatory. The unit is connected to chemicals. Knowledge of dangers associated to the specific chemicals used are recommended. The cooling liquid has the potential of being hot and under pressure. Full comprehension of the cooling system is mandatory. Necessary precautions should be observed to avoid injuries.

The cooling agent contains ethylene glycol that is a highly flammable product. Ethylene glycol can burn with an invisible flame that can cause serious burns and/or other injuries.

- Always handle the cooling agent carefully wearing appropriate safety clothing and eyeglasses.

The cooling agent can irritate the skin, the eyes and the mucous membranes.

- Always work in a well-ventilated area when handling the cooling agent; breathing in high concentrations of ethylene glycol can cause nausea.

Safety precaution

In case of contact with eyes and skin, rinse with water and consult a doctor.

- In case of ingestion, seek medical help immediately.

The cooling agent is under pressure when heated; removing the hoses when the coolant is hot can cause serious burns and/or other injuries.

- Wait until the coolant reaches an ambient temperature before removing the cables.

All potential dangers of handling cooling agents cannot be listed here.

- Consult manufacturer warnings and recommendations for safe handling of the cooling agent.

Appendix 6: Update Software

1. Download the up to date software from the Dana TM4 extranet site.
2. Once downloaded, execute the software package exe file. The appropriate file will be saved at the right location on the PC for ODIN usage.
3. Once executed, the original .exe file can be discarded.
4. Start ODIN4 using the ODIN 4 Server 1 shortcut.
5. Make sure that the ignition key is set to **ON** in order to establish communication with the MCU. The « Device Connected » in green text should be shown in the Status bar. If that is the case, go to step 7. Otherwise, continue on the next step.
6. If communication with the MCU was not established, select the **Configuration/Device communication** and select « Find Device » button. Wait until your CAN interface establish communication with the MCU by looking at the window under the « Find Device » button. Once communication is established, select it and then select « Apply » button.
7. Make sure that the ignition key is set to **OFF** and wait until «Device disconnected » in yellow is shown in the ODIN status bar. From a previous power ON, this could take up to 10 seconds maximum.
8. From the TM4 ODIN menu, select **Configuration/Flash program manager**.
Note: A message is displayed asking if you want to save the current workspace before programming another package; if you want to keep a copy of the workspace, save it as an .odn4 file. If you do not choose to save, the data will be cleared.
9. Select the application software from the **Select program** list.
10. Click **Start**; wait a few seconds until the start button name change to **Stop**.
11. Turn the ignition key to **ON** and wait for the software update to complete.
12. Once completed, TM4 ODIN disconnects from the server and will display a window to confirm the success of the package update.
13. Click the **OK** button to reconnect to the TM4 ODIN server.
14. At this point, the Basic TM4 ODIN file (UserInterface.odn4) can be opened from the ODIN menu **Package Files/ Workspaces**.
15. Contact TM4 Customer Service if you require help programming the system using TM4 ODIN.

Remove electrical connections

Safety precaution

WARNING

Safety instructions related to electrical removal/installation:

Electrical connections should be handled by fully trained personnel. High voltage, potentially as high as 750V for a HV system may be present and this should be seen as a dangerous and possibly lethal source.

Always follow recommended precautions when handling electrical equipment. The MCU stores electrical energy during operation and may retain it for some time after it is powered-off. It is highly recommended to ensure that the internal energy has dissipated before proceeding with the electrical disconnection of the unit.

ESD sensitive – do not touch connector pins.

- The internal electronics are sensitive to electrostatic discharges.

Risk of electric shock – do not open the product.

- The electrical installation of the system does not require the product to be opened or disassembled.

Risk of electric shock – capacitor stores hazardous energy.

- Wait 10 minutes after disconnecting all electrical power supplies prior to removing cables and/or servicing to ensure that internal product capacitors are discharged.

This product uses common mode capacitors between the high-voltage DC bus and the chassis. Some apparatuses can cause dangerous frame current to pass through these capacitors if they are connected to a high-voltage DC bus.

- Always measure the voltage between the high-voltage DC bus and the chassis using appropriate protection and insulation before manipulating the product.

This product uses differential mode capacitors between the positive high-voltage DC bus (+) and the negative high-voltage DC bus (-). Even when the product is disconnected from the high-voltage source, these capacitors can hold a voltage high enough to cause an electric discharge or death.

- Always measure the voltage between the positive high-voltage DC bus (+) and the negative high-voltage DC bus (-) using appropriate protection and insulation before manipulating the product.

Operations

1. Make sure to read and acknowledge the previous safety instruction before starting the following steps.
2. Disable the high-voltage and auxiliary batteries before disconnecting any cable, harness or hose.
3. Wait 10 minutes after disconnecting all electrical power supplies prior to removing cables and/or servicing to ensure that internal product capacitors are discharged.
4. Note the cables and connectors position for future installation.
5. Remove the coolant connection from the MCU. Use appropriate precautions.
6. Remove the DC connector of the high-voltage battery input of the MCU with precaution.
7. Remove the AC phases connector or connections of the MCU.
8. Remove the motor sensor connector from the MCU communication connector with precaution.
9. Remove the grounding strap with precaution.

Remove the MCU from the vehicle

Safety precaution

Safety instructions related to the charger removal:

WARNING

Follow the vehicle integrator's instructions to unmount the unit. You may be asked to keep the hardware for the reinstallation of the replacement charger. Chargers are not supplied with mounting hardware.

Care must be taken when handling the unit.

- This product must be handled by qualified and authorized personnel in accordance with applicable vehicle standards and industry practices. Always use appropriate insulation and protection before manipulating the product even when the product is disconnected from a high-voltage source.

Operations

1. Remove the mechanical fixation from the charger.
2. Remove the charger from the vehicle with precaution.

Install the new unit

Safety precaution

WARNING

Mishandling of this product may damage the product and/or cause injury or death.

- Do not attempt to open the charger for repairs; in case of damaged casing or suspected product malfunction, contact TM4.
- If using straps to lift the charger, ensure they do not touch or put pressure on the connectors.

When manipulating this product:

- Do not modify any part.
- Do not apply any external loads.

Operations

1. Make sure to acknowledge all the safety precaution needed to install the unit before handle it.
2. Refer to the integrator installation manual to install the unit according the integrator configuration.

Prepare and pack defective unit for shipping

CAUTION

This section describes the conditions that must be adhered to transporting TM4 products in order to ensure optimum performance once installed in a vehicle.

On leaving TM4 facilities, the product is void of all coolant and all connectors are covered. The packaging is designed to protect the content against damage from vibrations and impacts and is able to withstand maritime conditions during transportation.

TM4 products must be transported in well-ventilated facilities with adequate protections against dust and excessive humidity.

Note: The replacement unit comes with all necessary caps and protectors. It will arrive in fully equipped transports box.

While the products are in the original shipping crates, there are no precautions to take against electrostatic discharge (ESD); however, when packing/unpacking and manipulating the products, you must avoid touching the connector pins.

This page intentionally left blank.

For spec'ing or service assistance, call 1-877-777-5360 or visit our website at <http://www.dana.com>

Dana TM4 inc.
135, Joseph-Armand Bombardier, #25
Boucherville (Québec) J4B 8P1 Canada

www.dana.com/TM4

