

DANA D170 & D190 SERVICE PART NUMBER SUPERCESSIONS

PART NUMBER INFORMATION

DATE: 22/2/2016

TO: All Dana Aftermarket Group Customers

New D170 & D190 power divider service parts will supersede the original part numbers. Details are outlined in the recently issued **Service Bulletin DA012016**

These upgrade power divider components are to improve the durability performance of these axles.

- New service part numbers will supersede the old original service part numbers.
- Effective immediately all superseded level parts will cease to be supplied by Dana.
- New service part numbers are shown in the chart below.
- **All superseded stock should be returned to Dana Australia for credit.**
- New level parts outlined below should be ordered.
- **Please contact Dana Customer service on 1300 00 DANA for a return authority.**

Old Part Number	Part Description	New Part Number
132440	Input Shaft Thrust washer	132440-A
131333	V-Ring Seal	131333-A
513878	Manifold Parts Kit	513878-A

New Part Identification.

- Thrust washer 132440-A is made from a different material and its appearance has changed mainly to a redesign of the lubrication cavities.
- The V-Ring 131333-A, is now made of a high temperature Viton material, and is brown in colour it also comes with an O'ring also made of a high temperature Viton. This is used as a retaining device. The O'ring must be fitted over the V-Ring as shown below.



- Manifold parts kit 513878-A now has a high temperature rated hose, there is no change to the manifold assembly.

Current literature can be downloaded from www.spicerparts.com or at www.dana.com.au

Should you have any queries on the above or require further information, please contact Dana Australia on 1300 00 DANA

DRIVE AXLE INFO