

### AXLE TECH BULLETIN

DATE: 08/02/2021



For Axle Models: D170, D190, D590 (not applicable for FTP versions)

#### Screen Filter Assembly removed (Forward Axle only)

As of the beginning of January 2021, the Screen Filter Assembly is no longer installed to the forward drive head (Hose remains).

**Please note:**

On page 7 of the Illustrated Parts List AXIP-0057A, items 32 & 34 are now no longer fitted.



Also, on page 17 of the Service Manual AXSP-0057, install the hose as shown, but do NOT attach the screen and the hose clamp at the end.



From the 1<sup>st</sup> of January 2021 the Screen is no longer fitted.

**When rebuilding one of these axle units, we recommend also NOT to fit items 32 & 34 anymore.**

If you have any questions, please call Dana Australia on **1300 003 262** or e-mail [aus.spicer@dana.com](mailto:aus.spicer@dana.com) for more information.